

STATE OF NEW MEXICO
ENERGY AND MINERALS DEPARTMENT

OIL CONSERVATION DIVISION

P. O. BOX 2088
SANTA FE, NEW MEXICO 87501

Form C-103
Revised 10-1-78

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.O.S.	
LAND OFFICE	
OPERATOR	

5a. Indicate Type of Lease	
State <input type="checkbox"/>	Fee <input checked="" type="checkbox"/>
5. State Oil & Gas Lease No.	

SUNDRY NOTICES AND REPORTS ON WELLS

DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR.
USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.

1. <input type="checkbox"/> OIL WELL <input type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER- Water Disposal Well		7. Unit Agreement Name
2. Name of Operator Harvey E. Yates Company		8. Farm or Lease Name Richardson Fee
3. Address of Operator P. O. Box 1933, Roswell, New Mexico 88201		9. Well No. 2
4. Location of Well UNIT LETTER <u>K</u> <u>1980</u> FEET FROM THE <u>South</u> LINE AND <u>1980</u> FEET FROM THE <u>West</u> LINE, SECTION <u>5</u> TOWNSHIP <u>14S</u> RANGE <u>36E</u> N.M.P.M.		10. Field and Pool, or Wildcat Und. Austin Miss
11. Elevation (Show whether DF, RT, CR, etc.) 3963.1 GL		12. County Lea

16. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:

SUBSEQUENT REPORT OF:

PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>	CASING TEST AND CEMENT JOBS <input type="checkbox"/>	
		OTHER <u>Repair Tbg</u> <input type="checkbox"/>	

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work; SEE RULE 1103.

6/4/86 MI & RU CU. ND wellhead, NU BOP. RU & acidize tbg w/500 gal 15% HCL.
Unset pkr, POH & found hole in 100th jt from bottom.
6/6/86 Test in hole w/redressed nickle plated Lok-Set pkr + 338 jts of 2 3/8" plastic coated tbg. Test to 5000# above slips, found 1 hole in tbg & two collar leaks Displace annulus w/pkr fluid. ND BOP & NU Wellhead. Press test to 500# for 30 min, held o.k. Hook up well. RD & release CU. Witnessed by OCD Representative.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED Jayne Collins TITLE Production Analyst DATE 6/24/86

APPROVED BY ORIGINAL SIGNED BY JERRY SEXTON TITLE DISTRICT SUPERVISOR DATE JUN 26 1986
CONDITIONS OF APPROVAL, IF ANY:

100-443887-100