ENERGY AND MINERALS DEPARTMENT			
DISTRIBUTION P. O. BOX 2088 SANTA FE SANTA FE, NEW MEXICO 87501	Form C-103 Revised 10-1-78		
U.S.O.S. LAND OFFICE	Su. Indicate Type of State X 5. State Oil 6 Gas 1	Foo	
	LG 814		
SUNDRY NOTICES AND REPORTS ON WELLS 100 NOT USE THIS FORM FOR PROPOSALS TO FRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. 110 NOT USE THIS FORM FOR PROPOSALS TO FRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR.			
	7, Unit Agreement :		
Name of Operator Yates Petroleum Corporation	6. Farm or Lease 10 Woodpecker		
Address of Operator 207 South 4th St., Artesia, NM 88210	9. Well No. 5		
Location of Well UNIT LETTER G 1980 FLET FROM THE NORTH LINE AND 1980 FLET FROM	10. Field and Pool, Saundara Dar		
Fast $21$ 146 220		Saunders Permo Upper Per	
4211.9 <sup>†</sup> GR	12. County Lea		
Check Appropriate Box To Indicate Nature of Notice, Report or Ot NOTICE OF INTENTION TO: SUBSEQUEN	her Data T REPORT OF:		
IRFORM REMEDIAL WORK     PLUG AND ABANDON     REMEDIAL WORK       Importarily abandon     Commence drilling ophs.       ULL OR ALTER CABING     Change plans     Casing test and cement jqg       OTHER     OTHER	•	ABANDONMENT	
Concribe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including work) SET RULE 1103. Lost circulation at 10112'. Set lost circulation plugs as follows: Plug #1: 50 sacks Class "H" Thickset, 5# gilsonite & 1/4# flocele. WOC 6 hrs. Tagged bottom at 10153'. Plug #2: 100 sacks Class "H" Thickset, 5# gilsonite & 1/4# flocele. bottom at 10153'.	Plug set at l	0056.	
Plug #3: 100 sacks Class "H" Thickset, 5# gilsonite, 1/4# flocele & Tagged cement at 10153'. Plug #4: 50 sacks Class "H" Neat. Set at 10096'. Tagged cement at 10071'.			
Ran 248 jts of 5-1/2" 17# N-80 & K-55 casing as follows: ran 46 join 173 jts of 5-1/2" 17# K-55, 29 jts of 5-1/2" 17# N-80 (total 10086') 1-regular guide shoe set at 10071'. Insert float set at 10028'. Cem Poz, .6% Halad-22, .4% CFR-2 and 3# KCL. Compressive strength of ceme PD 9:45 AM 11-14-82. Bumped plug to 1000 psi, released pressure and 18 hrs. Ran Temperature and found top of cement at 6350' behind casi	of casing set mented w/1300 s ent - 1250 psi float held oka	at 10071'. sacks 50/50 in 12 hrs. av. WOC	
Thereby certify that the information above is true and complete to the best of my knowledge and belief.	12-1	.3-82	
ORIGINAL SIGNED BY JERRY SEXTON TITLE	DEC 1		

,

RECEIVED DEC 1 4 1982 HOBES OFFICE

r.

\* « .