

STATE OF NEW MEXICO
ENERGY AND MINERALS DEPARTMENT

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

OIL CONSERVATION DIVISION

P. O. BOX 2088
SANTA FE, NEW MEXICO 87501

Form C-103
Revised 10-1-78

5a. Indicate Type of Lease	
State <input checked="" type="checkbox"/>	Fee <input type="checkbox"/>
5. State Oil & Gas Lease No.	
V-128 & V-120	

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR.
USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER- <input type="checkbox"/>		7. Unit Agreement Name
2. Name of Operator MWJ PRODUCING COMPANY		8. Farm or Lease Name Baum 17 "B" State Com
3. Address of Operator 1804 First National Bank Bldg Midland, Texas 79701		9. Well No. 1
4. Location of Well UNIT LETTER P 660 FEET FROM THE South 660 FEET FROM East 17 TOWNSHIP 14S RANGE 33E NMPM.		10. Field and Pool, or Wildcat Baum Upper Penn
15. Elevation (Show whether DF, RT, GR, etc.) 4230' GL		12. County Lea

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:

PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>	REMEDIAL WORK <input checked="" type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>	CASING TEST AND CEMENT JOB <input type="checkbox"/>	OTHER Perf & Acd <input checked="" type="checkbox"/>

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

12/20/85: SITP 0. PU tbg, parted. POOH w/74 jts tbg, had body break. LD broken jt & ran 4-11/16" OS w/2-7/8" grappel. TIH w/74 jts tbg, ran to 306th jt, latched on & pulled off. TOOH RIH w/2-3/8" grappel, latched on & POOH. LD fish & fshg tools. RIH w/pkr. Set w/300 jts in well w/18000# tension, top of pkr @ 9768'. RU swab & swbd.
12/21/85: TP 0. Chk'd FL @ 8200'. Swbd dry in 2 hrs.
12/22/85: SD.
12/23/85: Rel pkr & ran 6 jts, latched on to BP. Rel & POOH. LD BP & pkr. Ran perf sub w/bull plug, Baker Model R-3 pkr, pump cavity & drifted 271 jts 2-3/8" tbg in well.
12/24/85: Ran addt'l 30 jts & w/301st jt in well, set pkr @ 9827.06' w/10000# tension. Flanged up. RU kill truck & pmpd 50 bbls 2% KCL wtr. Dropped std vlv. Circ w/addt'l 220 bbls KCL wtr. Press to 1200 psi, OK. Rel press, RD & MO.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED Pat Drexler TITLE Pat Drexler - Agent DATE 12/26/85

ORIGINAL SIGNED BY JERRY SEXTON
DISTRICT 1 SUPERVISOR

APPROVED BY _____ TITLE _____ DATE _____

CONDITIONS OF APPROVAL, IF ANY:

DEC 31 1985

RECEIVED

DEC 30 1985

U.S. HOUSE OF REPRESENTATIVES