

Submit 3 Copies
to Appropriate
District Office

State of New Mexico
Energy, Minerals and Natural Resources Department

Form C-103
Revised 1-1-89

DISTRICT I
P.O. Box 1980, Hobbs NM 88241-1980

DISTRICT II
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III
1000 Rio Brazos Rd., Aztec, NM 87410

OIL CONSERVATION DIVISION

P.O. Box 2088
Santa Fe, New Mexico 87504-2088

WELL API NO. 30-025-28023
5. Indicate Type of Lease STATE <input type="checkbox"/> FEE <input checked="" type="checkbox"/>
6. State Oil & Gas Lease No.

SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)	
1. Type of Well: OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER	7. Lease Name or Unit Agreement Name TENNECO HARRIS
2. Name of Operator GP II ENERGY CORPORATION	8. Well No. 1
3. Address of Operator P.O. BOX 50682 MIDLAND, TEXAS 79702	9. Pool name or Wildcat BRONCO WOLFCAMP
4. Well Location Unit Letter <u>I</u> : <u>2310</u> Feet From The <u>SOUTH</u> Line and <u>626</u> Feet From The <u>EAST</u> Line Section <u>2</u> Township <u>13-S</u> Range <u>38-E</u> NMPM <u>LEA</u> County	
10. Elevation (Show whether DF, RKB, RT, GR, etc.) 3791' GR	

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☒
TEMPORARILY ABANDON ☐ CHANGE PLANS ☐
PULL OR ALTER CASING ☐
OTHER: ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐ ALTERING CASING ☐
COMMENCE DRILLING OPNS. ☐ PLUG AND ABANDONMENT ☐
CASING TEST AND CEMENT JOB ☐
OTHER: ☐

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

SET CIBP @ 9000'; CAP W/ 35' CMT.
CIRC HOLE W/ 10# BRINE W/ 25# SALT GEL PER BBL.
SPOT 50 SXS PLUG; 50' IN & 50' OUT CSG STUB; WOC & TAG.
SPOT 50 SXS PLUG 4709'-4609' (8-5/8" SHOE); WOC & TAG.
SPOT 45 SXS PLUG 396'-296' (13-3/8" SHOE); WOC & TAG. *will need to perf 8 5/8 @ 396*
SPOT 15 SXS 30' -SURFACE.
INSTALL DRY HOLE MARKER.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE *Joey Fields* TITLE _____ DATE _____
TYPE OR PRINT NAME _____ TELEPHONE NO. _____

(This space for State Use)

APPROVED BY _____ TITLE _____ DATE JUL 19 1996
CONDITIONS OF APPROVAL, IF ANY: