

Submit 3 Copies
to Appropriate
District Office

State of New Mexico
Energy, Minerals and Natural Resources Department

Form C-103
Revised 1-1-89

DISTRICT I
P.O. Box 1960, Hobbs, NM 88240

DISTRICT II
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III
1000 Rio Brazos Rd., Aztec, NM 87410

OIL CONSERVATION DIVISION
P.O. Box 2088
Santa Fe, New Mexico 87504-2088

WELL API NO.	30-025-28082
5. Indicate Type of Lease	STATE ☒ FEE ☐
6. State Oil & Gas Lease No.	K-3657
7. Lease Name or Unit Agreement Name	State of NM T
8. Well No.	3
9. Pool name or Wildcat	Baum Upper Penn

SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)	
1. Type of Well: OIL WELL ☐ GAS WELL ☒ OTHER	
2. Name of Operator Louis Dreyfus Natural Gas Corporation	
3. Address of Operator 14000 Quail Springs Parkway, Ste. 600, Oklahoma City, OK	
4. Well Location Unit Letter D : 660 Feet From The North Line and 520 Feet From The West Line Section 4 Township 14S Range 33E NMPM Lea County	
10. Elevation (Show whether DF, RKB, RT, GR, etc.) 4241'	

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data	
NOTICE OF INTENTION TO:	SUBSEQUENT REPORT OF:
PERFORM REMEDIAL WORK ☐	REMEDIAL WORK ☐
TEMPORARILY ABANDON ☐	ALTERING CASING ☐
PULL OR ALTER CASING ☐	COMMENCE DRILLING OPNS. ☐
OTHER: ☐	PLUG AND ABANDONMENT ☒
	CASING TEST AND CEMENT JOB ☐
	OTHER: ☐

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

- (1) 7-23-01 Set 5-1/2" cmt. retainer @ 7950', sqz 150 sx cmt. from 9732'-8000', WOC, pressure test to 1000 PSI. Ok.
- (2) 7-23-01 Circulation w/ mud gel.
- (3) 7-23-01 Spot 25 sx cmt. on top the 5-1/2" cmt. retainer from 7950'-7729'.
- (4) 7-24-01 Cut 5-1/2" csg. @ 6180', spot 25 sx cmt. from 6235'-6105', WOC & tag @ 6115'.
- (5) 7-25-01 Spot 30 sx cmt. from 4150'-4050', 2-5/8" shoe, WOC, tag @ 4030'.
- (6) 7-25-01 Spot 30 sx cmt. from 1740'-1640', no tag.
- (7) 7-25-01 Spot 30 sx cmt. from 390' - 290', WOC & tag @ 268'. OK.
- (8) 7-25-01 Spot 15 sx cmt. from 50' - 3' Surface plug.

Approved as to plugging of the Well Bore.
Liability under bond is retained until
surface restoration is completed.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE [Signature] TITLE Agent DATE 08/07/01
TYPE OR PRINT NAME _____ TELEPHONE NO. _____

(This space for State Use)

APPROVED BY [Signature] TITLE CC FIELD REPRESENTATIVE II/STAFF MANAGER DATE JAN 16 2003
CONDITIONS OF APPROVAL, IF ANY: _____