Submit 3 Copies to Appropriate District Office

## State of New Mexico Energy, . . . . erals and Natural Resources Department

Form C-103 Revised 1-1-89

DISTRICT I P.O. Box 1980, Hobbs, NM 88240

OIL CONSERVATION DIVISION P.O. Box 2088

WELL API NO. 30-025-28172

STRICT II Santa Fe, New Mexico 87504-2088	
D. Drawer DD, Artesia, NM 88210	5. Indicate Type of Lease STATE X FEE
STRICT III O Rio Brazos Rd., Azzec, NM 87410	6. State Oil & Gas Lease No. LC 814
AND DEPORTS ON WELLS	
SUNDRY NOTICES AND REPORTS ON WELLS DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT"  (FORM C-101) FOR SUCH PROPOSALS.)	7. Lease Name or Unit Agreement Name
Type of Well: Oil	Woodpecker SY State
Name of Operator YATES PETROLEUM CORPORATION (505) 748-1471	8. Well No.
Address of Operator 105 South 4th St., Artesia, New Mexico 88210	9. Pool name or Wildcat Saunders Permo Upper Penn
Well Location  Unit Letter F : 1980 Feet From The North Line and 198	0 Feet From The West Line
21 Township 14S Range 33E	NMPM Lea County
10. Elevation (Show whether DF, RKB, RT, GR, etc.)	
//////////////////////////////////////	<u> </u>
Check Appropriate Box to Indicate Nature of Notice, I	Report, or Other Data
NOTICE OF INTENTION TO:	BSEQUENT REPORT OF:
RFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORK	ALTERING CASING
MPORARILY ABANDON CHANGE PLANS COMMENCE DRILLII	
JLL OR ALTER CASING CASING TEST AND	CEMENT JOB L
·	· ·
THER: Propose to drill out CIBP's & test X OTHER:	
THER: Propose to drill out CIBP's & test X OTHER:  perfs.  12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, incompared SEE RULE 1103.	
THER: Propose to drill out CIBP's & test X OTHER:  perfs.  12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, inc.	forations 9883-9911' and 9936-
THER: Propose to drill out CIBP's & test X OTHER:  perfs.  12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, incomplete 1103.  Proposed to drill out CIBP's at 9870' and 9835'; test per	forations 9883-9911' and 9936-
THER: Propose to drill out CIBP's & test X OTHER:  perfs.  2. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, incompared to drill out CIBP's at 9870' and 9835'; test per	forations 9883-9911' and 9936-
THER: Propose to drill out CIBP's & test X OTHER:  perfs.  2. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, incompared to drill out CIBP's at 9870' and 9835'; test per	forations 9883-9911' and 9936-
THER: Propose to drill out CIBP's & test X OTHER:  perfs.  2. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, incompared to drill out CIBP's at 9870' and 9835'; test per	forations 9883-9911' and 9936-
THER: Propose to drill out CIBP's & test X OTHER:  perfs.  2. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, incompared to drill out CIBP's at 9870' and 9835'; test per	forations 9883-9911' and 9936-
THER: Propose to drill out CIBP's & test X perfs.  12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, incomplete to drill out CIBP's at 9870' and 9835'; test per 9944'. Add perforations at 9953-9955'. Acidize, swab a	forations 9883-9911' and 9936- nd evaluate.
THER: Propose to drill out CIBP's & test perfs.  12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, incomplete to drill out CIBP's at 9870' and 9835'; test per 9944'. Add perforations at 9953-9955'. Acidize, swab a liberaty certify that the information above is true and complete to the best of my knowledge and belief.	forations 9883-9911' and 9936- nd evaluate.
THER: Propose to drill out CIBP's & test X perfs.  2. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, incomplete to drill out CIBP's at 9870' and 9835'; test per 9944'. Add perforations at 9953-9955'. Acidize, swab a	forations 9883-9911' and 9936- nd evaluate.