

Submit 3 Copies To Appropriate District
Office
District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 South First, Artesia, NM 88210
District III
1000 Rio Brazos Rd., Aztec, NM 87410
District IV
2040 South Pacheco, Santa Fe, NM 87505

State of New Mexico
Energy, Minerals and Natural Resources

Form C-103
Revised March 25, 1999

OIL CONSERVATION DIVISION
2040 South Pacheco
Santa Fe, NM 87505

WELL API NO. 30-025-28178
5. Indicate Type of Lease STATE <input type="checkbox"/> FEE <input checked="" type="checkbox"/>
6. State Oil & Gas Lease No. Fee lease
7. Lease Name or Unit Agreement Name: RICHARDSON FEE
8. Well No. 3
9. Pool name or Wildcat McDonald Pennsylvanian, West

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH
PROPOSALS.)

1. Type of Well: Oil Well <input checked="" type="checkbox"/> Gas Well <input type="checkbox"/> Other
2. Name of Operator Harvey E. Yates Company
3. Address of Operator P.O. Box 1933, Roswell, New Mexico 88202
4. Well Location Unit Letter <u>D</u> : <u>660</u> feet from the <u>NORTH</u> line and <u>660</u> feet from the <u>WEST</u> line Section <u>5</u> Township <u>14 S</u> Range <u>36 E</u> NMPM County <u>LEA</u>
10. Elevation (Show whether DR, RKB, RT, GR, etc.) 3973.5' GL (15' kb)

11. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☒
TEMPORARILY ABANDON ☐ CHANGE PLANS ☐
PULL OR ALTER CASING ☐ MULTIPLE COMPLETION ☐
OTHER: ADD PERFORATIONS ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐ ALTERING CASING ☐
COMMENCE DRILLING OPNS. ☐ PLUG AND ABANDONMENT ☐
CASING TEST AND CEMENT JOB ☐
OTHER: ☐

12. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or recompilation.

Harvey E. Yates Company proposes to do as follows:

1. Set CIBP @ 10,300' + 35' cmt.
2. Circulate 9# mud.
3. Cut & pull appx 9,500' - 5 1/2" csg.
4. Spot 100' plug (50' in/out) from 9,550' - 9,520'. Tag plug.
5. Spot 100' plug @ 7,100' - 7,000'. Tag plug.
6. Spot 100' plug @ 4,650' - 4,550'. Tag plug.
7. Spot 100' cmt from 2,100' - 2,000'.
8. Spot 100' cmt from 430' - 330'. - TAG
9. Set 50 sx surface plug & install dry hole marker.

THE COMMISSION MUST BE NOTIFIED 24 HOURS PRIOR TO THE BEGINNING OF PLUGGING OPERATIONS FOR THE C-103 TO BE APPROVED.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Jeanetta Atkinson TITLE Production Analyst DATE 12/05/02

Type or print name Jeanetta Atkinson Telephone No. 505-623-6601
(This space for State use)

APPROVED BY _____ TITLE _____ DATE DEC 19 2002
Conditions of approval, if any: