

DISTRICT I
P.O. Box 1980, Hobbs, NM 88240

DISTRICT II
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III
1000 Rio Brazos Rd., Aztec, NM 87410

OIL CONSERVATION DIVISION

P.O. Box 2088
Santa Fe, New Mexico 87504-2088

WELL API NO.	30-25-28205
5. Indicate Type of Lease	STATE ☒ FEE ☐
6. State Oil & Gas Lease No.	E-7353-2
7. Lease Name or Unit Agreement Name	
Saunders State	
8. Well No.	1
9. Pool name or Wildcat	Saunders Premo (Upper Penn)
10. Elevation (Show whether DP, RKB, RT, GR, etc.)	
4228 GR.	

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT"
(FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well: OIL WELL ☒ GAS WELL ☐ OTHER ☐	2. Name of Operator Eclipse Oil & Gas, Inc.
3. Address of Operator P.O. Box 15122 Odessa, TX 79768	4. Well Location Unit Letter <u>N</u> : <u>660</u> Feet From The <u>South</u> Line and <u>1980</u> Feet From The <u>West</u> Line Section <u>9</u> Township <u>14S</u> Range <u>33E</u> NMPM <u>Lea</u> County <u></u>
10. Elevation (Show whether DP, RKB, RT, GR, etc.)	
4228 GR.	

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:	SUBSEQUENT REPORT OF:
PERFORM REMEDIAL WORK ☐	REMEDIAL WORK ☐
TEMPORARILY ABANDON ☐	ALTERING CASING ☐
PULL OR ALTER CASING ☐	COMMENCE DRILLING OPNS. ☐
OTHER: ☐	PLUG AND ABANDONMENT ☐
	CASING TEST AND CEMENT JOB ☐
	OTHER: ☐

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.
(NOTIFY CONSERVATION COMMISSION (505) 393-6161 24HRS. BEFORE OPERATIONS BEGIN.)

(1) MIRU Unit, pressure up on tbq to 500#, POH w/ rods and tbq.

(2) Set CIBP on WL @ 9750' and cap w/ 35' W DUMP BAILER / 25SX IF SPOTED W/ TBG. - TAG

(3) TIH w/ tbq., circ. hole w/ 10# BW w/ 25# SWG per bbl. Pump 25sx. plug @ 7000', POH.

(4) Stretch, cut and lay down 5 1/2" csg.

(5) TIH, Pump 50' in & 50' out plug across 5 1/2" stub (TAG W/ TBG.)

(6) Pump 100' plug across 8-5/8" shoe @ 4179' (TAG W/ TBG.)

(7) Pump 100' plug across 13-3/8" shoe @ 424' (TAG W/ TBG.)

(8) Pump 15sx. surface plug

(9) Install dry hole marker

SALT PLUG - 1936' - 1836'

SIGNATURE Frelan Fields TITLE Agent DATE 9/18/00
(915) 366-1852
TELEPHONE NO.

TYPE OR PRINT NAME Frelan Fields

(This space for State Use)

APPROVED BY _____ DATE OCT 2 2000

CONDITIONS OF APPROVAL, IF ANY: