

Submit 3 Copies
to Appropriate
District Office

State of New Mexico
Energy, Minerals and Natural Resources Department

Form C-103
Revised 1-1-89

DISTRICT I
P.O. Box 1980, Hobbs, NM 88240

DISTRICT II
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III
1000 Rio Brazos Rd., Aztec, NM 87410

OIL CONSERVATION DIVISION
P.O. Box 2088
Santa Fe, New Mexico 87504-2088

WELL API NO.
30-025-28206

5. Indicate Type of Lease
STATE ☒ FEE ☐

6. State Oil & Gas Lease No.

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT"
(FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well:
OIL WELL ☒ GAS WELL ☐ OTHER

2. Name of Operator
Tamarack Petroleum Company, Inc.

3. Address of Operator
500 W. Texas - Suite 1485, Midland, Texas 79701

4. Well Location
Unit Letter J : 1980 Feet From The South Line and 1980 Feet From The East Line

Section 16 Township 14-S Range 33-E NMPM Lea County

10. Elevation (Show whether DF, RKB, RT, GR, etc.)
4224' KB

7. Lease Name or Unit Agreement Name

Saunders A State

8. Well No.
1

9. Pool name or Wildcat
Saunders Permo Upper Penn.

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☐
TEMPORARILY ABANDON ☐ CHANGE PLANS ☐
PULL OR ALTER CASING ☐
OTHER: Plug back & test Wolfcamp ☒

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐ ALTERING CASING ☐
COMMENCE DRILLING OPNS. ☐ PLUG AND ABANDONMENT ☐
CASING TEST AND CEMENT JOB ☐
OTHER: ☐

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

1. Cut off tubing above stuck anchor @ 9785'.
2. Set CIBP @ 9780'. (Current perforations are 9812' - 9966' in Bough A, B & C zones)
3. Perforate Wolfcamp @ 9546, 9547, 9548, 9558, 9559, 9561, 9562, 9563, 9564, 9620, 9622, 9624, 9626, 9682, 9684, 9686
4. Acidize and swab test perfs 9546' - 9686'.
5. Perforate Wolfcamp @ 9441, 9442, 9443, 9454, 9455, 9456, 9461, 9462, 9477, 9478, 9479, 9480
6. Acidize and swab test perfs 9441' - 9480'.
7. Perforate Wolfcamp @ 9130, 9131, 9136, 9137, 9144, 9145, 9146, 9149, 9156, 9157
8. Acidize and swab test perfs 9130' - 9157'.
9. If production is indicated, RIH w/production string and place well on production.

Note: Work currently in progress 1-14-98 per telephone discussion with Paul Kautz. If unsuccessful, will file plugging proposal which will include dumping 35' cement plug above CIBP.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Wayne Green TITLE Production Agent DATE 01/14/98

TYPE OR PRINT NAME T. Wayne Green TELEPHONE NO. 915/683-5474

(This space for State Use)

APPROVED BY WILLIAMS
DISTRICT SUPERVISOR

TITLE DATE

CONDITIONS OF APPROVAL, IF ANY:

