

DISTRICT I

P.O. Box 1980, Hobbs NM 88240

DISTRICT II

P.O. Drawer DD, Artesia NM 88210

DISTRICT III

1000 Rio Brazos Rd., Aztec NM 87410

State of New Mexico
Energy, Minerals and Natural Resources Department

OIL CONSERVATION DIVISION

P.O. Box 2088
Santa Fe, New Mexico 87504-2088

WELL API NO.	30-025-28262
5. Indicate Type of Lease	
State	<input checked="" type="checkbox"/> FEE <input type="checkbox"/>
6. State Oil & Gas Lease No.	
LG-814	
7. Lease Name or Unit Agreement Name	
WOODPECKER SY STATE	
8. Well No.	7
9. Pool Name or Wildcat	
Saunders Perno Upper Penn	

SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)	
1. Type of Well: OIL <input type="checkbox"/> GAS <input type="checkbox"/> WELL <input checked="" type="checkbox"/> WELL <input type="checkbox"/> OTHER <input type="checkbox"/>	
2. Name of Operator Yates Petroleum Corporation	
3. Address of Operator 105 South 4th., Artesia, NM 88210	
4. Well Location Unit Letter <u>D</u> : <u>660</u> Feet From The <u>NORTH</u> Line and <u>660</u> Feet From The <u>WEST</u> Line Section <u>21</u> Township <u>14S</u> Range <u>33E</u> NMPM <u>LEA</u> COUNTY	
10. Elevation (Show whether DF, RKB, RT, GR, etc.) 4222.9' GR	

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:	
PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input checked="" type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	
OTHER <input type="checkbox"/>	


SUBSEQUENT REPORT OF:	
REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
CASING TEST AND CEMENT JOB <input type="checkbox"/>	
OTHER <input type="checkbox"/>	

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

YATES PETROLEUM CORPORATION proposes to plug & abandon as follows:

1. RU PU & plugging equipment. Load tubing & casing. Install BOP.
2. Production record shows no equipment in well.
3. Pick up workstring & GIH to 9800'.
4. Set CIBP @ 9735' & cap w/ 35' of cement.
5. Freepoint 5-1/2" casing - cut & pull casing. TOC is 7120' per CBL.
6. GIH w/ tubing open ended to 7784'. Load hole w/ salt gel plugging mud.
7. Spot 25 sk cement plug across Abo top - 7734' - from 7784-7684'.
8. Pull up & spot 35 sk plug across 5-1/2" casing stub (7000' +/-). Pull up, WOC, & tag plug at least 50' above stub.
9. Pull up & spot 35 sk plug across Glorieta top - 5571'.
10. Pull up & spot 35 sk plug across 8-5/8" csg shoe (4197'). WOC & tag plug @ 4147' or higher. If no tag, respot plug, WOC, & tag. → SPOT 100' PLUG F/1950'-1850' (T.O.S. PLUG)
11. Pull up & spot 35 sk plug across 13-3/8" shoe depth - 458'. — TAG
12. Set 15 sk plug @ surface & install regulation abandonment marker.

THE COMMISSION MUST BE NOTIFIED 24 HOURS PRIOR TO THE BEGINNING OF PLUGGING OPERATIONS FOR THE C-103 TO BE APPROVED.



I hereby certify that the information above is a true and complete to the best of my knowledge and belief.

SIGNATURE Donna Clack TITLE Operations Technician DATE 3/26/02
TYPE OR PRINT NAME DONNA CLACK TELEPHONE NO. 505-748-1471

(This space for State Use)

APPROVED BY GARY W. WINK DATE APR 02 2002
CONDITIONS OF APPROVAL, IF ANY: OC FIELD REPRESENTATIVE II/STAFF MANAGER