

DISTRICT I
P.O. Box 1980, Hobbs, NM 88240

DISTRICT II
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III
1000 Rio Brazos Rd., Aztec, NM 87410

OIL CONSERVATION DIVISION

P.O. Box 2088
Santa Fe, New Mexico 87504-2088

WELL API NO.

5. Indicate Type of Lease

STATE ☒

FEE ☐

6. State Oil & Gas Lease No.

K-4177

7. Lease Name or Unit Agreement Name

State "8"

8. Well No.

4

9. Pool name or Wildcat

Baum (U. Penn)

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT"
(FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well:

OIL
WELL ☒

GAS
WELL ☐

OTHER ☐

2. Name of Operator

Coastal Oil & Gas Corporation

3. Address of Operator

P. O. Box 235, Midland, Texas 79702

4. Well Location

Unit Letter G : 2310 Feet From The East Line and 1830 Feet From The North Line

Section 8 Township 14-S Range 33-E NMPM Lea County

10. Elevation (Show whether DF, RKB, RT, GR, etc.)

4249.9 GR

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐

PLUG AND ABANDON ☐

TEMPORARILY ABANDON ☐

CHANGE PLANS ☐

PULL OR ALTER CASING ☐

OTHER: ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐

ALTERING CASING ☐

COMMENCE DRILLING OPNS. ☐

PLUG AND ABANDONMENT ☒

CASING TEST AND CEMENT JOB ☐

OTHER: ☐

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

NOTE: This well was TA in October 1987 by setting a CIBP at 9830' and topping with 35' of cement, then setting a CIBP at 9408' and topping with 35' of cement.
3-14-89 RU Plugging Unit. GIH with tbg and displace hole with 10 PPG mud. POOH.
3-15-89 Weld on to 5-1/2" csg, pull stretch, indicated free point at 6000'. Shot csg at 6719', no success. Shot csg at 5984', pulled free. Start LD csg.
3-16-89 Finish LD 5-1/2" csg, LD total of 144 jts (5980'). GIH with tbg to 6753' and spot 25 sack plug. PU to 6038' and spot 25 sack plug at stub.
3-17-89 GIH with tbg, tag stub plug at 5920'. PU to 4166' and spot 35 sack plug. WOC 4 hrs and tag plug at 4050'. PU to 1776' and spot 30 sack plug. Spot 10 sack surface plug. Installed P&A Marker. Well P&A'd.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE

Bobby L. Smith

TITLE

Area Superintendent

DATE

3-20-89

(915)

TYPE OR PRINT NAME

Bobby L. Smith

TELEPHONE NO.

682-7925

(This space for State Use)

APPROVED BY

[Signature]

TITLE

OIL & GAS INSPECTOR

DATE

APR 18 1989

CONDITIONS OF APPROVAL, IF ANY:

R N

B

RECEIVED

MAR 22 1989

OCD
HOBAS OFFICE