

STATE OF NEW MEXICO
ENERGY AND MINERALS DEPARTMENT

OIL CONSERVATION DIVISION

P. O. BOX 2088
SANTA FE, NEW MEXICO 87501

Form C-103
Revised 10-1-78

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

5a. Indicate Type of Lease	
State ☒	Fee ☐
5. State Oil & Gas Lease No.	
LG-8294	

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR.
USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL ☒ WELL GAS ☐ WELL OTHER ☐		7. Unit Agreement Name
2. Name of Operator Coastal Oil & Gas Corporation		8. Farm or Lease Name State "22"
3. Address of Operator P. O. Box 235 Midland, Texas 79702		9. Well No. 2
4. Location of Well UNIT LETTER 0, 660 FEET FROM THE South LINE AND 1340 FEET FROM THE East LINE, SECTION 22 TOWNSHIP 14-S RANGE 32-E N.M.P.M.		10. Field and Pool, or Wildcat Tulk (Penn)
15. Elevation (Show whether DF, RT, GR, etc.) 4317' KB		12. County Lea

16. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:

PERFORM REMEDIAL WORK ☐	PLUG AND ABANDON ☐	REMEDIAL WORK ☐	ALTERING CASING ☐
TEMPORARILY ABANDON ☐	CHANGE PLANS ☐	COMMENCE DRILLING OPS. ☐	PLUG AND ABANDONMENT ☐
PULL OR ALTER CASING ☐	OTHER ☐	CASING TEST AND CEMENT JOBS ☐	OTHER Completion ☒

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work; SEE RULE 1103.

12-29-83 Rig up. RIH w/bit & DC on tbg. Tag @ 9854 SD.
12-30-83 Drill float collar & cmt. to 9866'. Circ. hole w/2% KCl water. Press to 1000# - OK. POOH. Ran GR/CBL 9866-7676'.
12-21-83 RIH w/pkr. Spot acid. Set pkr @ 9805'. Perf 9847-55 2 SPF w/tbg gun. Treat w/2000 gal 15% acid. Treated 0.9 BPM @ 4800 psi. Pkr failed. Flow back 35 BF in 2 hrs. SD.
1-01-84 Swab 72 BF in 5 hr. Unset pkr. Swab to 4500'. SD.
1-02-84 POOH w/pkr. PU new pkr & RIH. Set @ 9742'. Swab 2½ hr rec. 42 BF.
1-03-84 Swabbing.
1-04-84 Treat w/1500 gal 15% NE-FE acid. Treated 2.5 BPM @ 200 psi. Swab 60 BF in 6 hr.
1-05-84 Swabbing
1-06-84 Swab 6 hr. RIH w/BHP bomb. SI
1-07-84 SI
1-08-84 SI
1-09-84 Pulled BHP bomb. Swab 36 BF in 5 hr. Rel. pkr. Kill well. POOH.
1-10-84 RIH w/RTTS & RBP. Set RBP @ 9837'. Spot acid. Set RTTS @ 9665'.
Perf 9765-73', 84-89', 9805-14', 22-26' 1 SPF w/tbg gun. Treat w/6000 gal 15% NE-FE acid. Treated 3.1 BPM @ 4000 psi.
1-11-84 Swabbing

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED D. J. Campbell TITLE _____ DATE _____

APPROVED BY ORIGINAL SIGNED BY JERRY SEATON TITLE Sr. Petroleum Engineer DATE FEB 2 1984
DISTRICT SUPERVISOR
CONDITIONS OF APPROVAL, IF ANY: