

Submit 3 Copies  
to Appropriate  
District Office

State of New Mexico  
Energy Minerals and Natural Resources Department

Form C-103  
Revised 1-1-89

DISTRICT I  
P.O. Box 1980, Hobbs, NM 88240

DISTRICT II  
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III  
1000 Rio Brazos Rd., Aztec, NM 87410

OIL CONSERVATION DIVISION  
P.O. Box 2088  
Santa Fe, New Mexico 87504-2088

WELL API NO. 30-025-28486
5. Indicate Type of Lease STATE <input checked="" type="checkbox"/> FEE <input type="checkbox"/>
6. State Oil & Gas Lease No. LG 1623
7. Lease Name or Unit Agreement Name Raven YH State
8. Well No. 1
9. Pool name or Wildcat Tulk Penn

SUNDRY NOTICES AND REPORTS ON WELLS  
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A  
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT"  
(FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well: OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER	10. Elevation (Show whether DF, RKB, RT, GR, etc.) 4315.2' GR
2. Name of Operator YATES PETROLEUM CORPORATION	
3. Address of Operator 105 South Fourth Street - Artesia, NM 88210	
4. Well Location Unit Letter P : 560 Feet From The South Line and 560 Feet From The East Line Section 33 Township 14S Range 32E NMPM Lea County	

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data	
NOTICE OF INTENTION TO:	SUBSEQUENT REPORT OF:
PERFORM REMEDIAL WORK <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	CASING TEST AND CEMENT JOB <input type="checkbox"/>
OTHER: <input type="checkbox"/>	OTHER: <input type="checkbox"/>
PLUG AND ABANDON <input checked="" type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
CHANGE PLANS <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

1. Notify NMOCD, Hobbs, prior to job.
2. Set CIBP at 9650'+/- and dump 35' cmt on top.
3. Cut & pull 5 1/2" csg. TCMT 6250' by CBL.
4. Set 100' (25 sx mini) cmt plug across 5 1/2" stub. WOC & tag.
5. Set 100' (25 sx mini) cmt plug across Glorieta top at 5550'.
6. Set 100' (25 sx mini) cmt plug across 8 5/8" csg shoe at 4195'. WOC & tag.
7. Set 100' (25 sx mini) cmt plug across Rustler top at 1535'.
8. Set 10 sx surface plug & install P&A marker.

NOTICE TO LANDLORDS  
FOR THE PURPOSE OF  
OBTAINING A LEASE  
FOR THE OIL AND GAS  
TO BE PRODUCED

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Rusty Klein (by Pamela E. Evans) TITLE Production Clerk DATE 10-21-94  
TYPE OR PRINT NAME Rusty Klein / PAMELA EVANS TELEPHONE NO. 505-748-1471

(This space for State Use)

OCT 25 1994

APPROVED BY \_\_\_\_\_ TITLE \_\_\_\_\_ DATE \_\_\_\_\_