STATE OF NEW MEXICO ENERGY AND MINERALS DEPARTMENT

OIL CONSERVATION DIVISION P. O. BOX 2088 SANTA FE, NEW MEXICO 87501	Form C-103 · Revised 10-1-78
FILE U.S. G.S. LANG OFFICE	State X Fee State Oil & Gas Lease No.
SUNDRY NOTICES AND REPORTS ON WELLS	LG 1469
USE "APPLICATION FOR PERMIT " (FORM C-101) FOR SUCE THE	7. Unit Agreement Name
Name of Operator	8. Form or Lease Name Le Gulf
Harvey E. Yates Company Address of Operator	9. Well No.
P. O. Box 1933, Roswell, New Mexclo 88201	#1 10. Field and Pool, or Wildcat
Location of Well UNIT LETTER 1980 FEET FROM THE SOUTH LINE AND 660	Und. Baum Upper Penn
THE West LINE, SECTION 18 TOWNSHIP 145 RANGE SEE NAMES	
15. Elevation (Show whether DF, RT, GR, etc.) 4267 GR	12. County Lea
Check Appropriate Box To Indicate Nature of Notice, Report of O SUBSEQUER NOTICE OF INTENTION TO: REMPORM REMEDIAL WORK TEMPORARILY ABANDON PULL OR ALTER CASING OTHER OTHER 7. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including the complete dates).	ALTERING CASING PLUG AND ABANDONMENT
PROCEDURE 1. CIBP @ 9680' 2. TOC est. @ 9662' 3. Free Point & Cut 5 1/2" casing. 4. Pump 100' plug @ cut off (50' in & 50' out of cut off) & tag. 5. Set 100' plug from 9315' to 9215'. (Wolfcamp). 6. Set 100' plug from 7724' to 7624'. (Abo). 7. Set 100' plug from 5937' to 5837'. (Glorieta). 8. Set 100' plug @ shoe of Intermediate casing - 4015' (50' in & 9. Set 100' plug from 1671' to 1571' (Top of Salt). 10. Set 10 sx plug @ surface w/dry hole marker.	
Per Jerry Sexton 5/21/84. THE COMMISSION MUST BE NOTIFIED 24 HOURS FROM TO THE ELEINNING OF PLUGGING OPERATIONS FOR THE C-103 TO BE APPROVED.	

ORIGINAL SIGNED BY JERRY SEXTON

PRODUCTS OF APPROVAL, IF ANY:

MAY 23 1984
HOBBS CORICE