

STATE OF NEW MEXICO
ENERGY AND MINERALS DEPARTMENT

OIL CONSERVATION DIVISION

P. O. BOX 2088

SANTA FE, NEW MEXICO 87501

Form C-103
Revised 10-1-73

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

5a. Indicate Type of Lease
State ☒ Fee ☐
5. State Oil & Gas Lease No.

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR.
USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

1. <input checked="" type="checkbox"/> OIL WELL <input type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER-	7. Unit Agreement Name
2. Name of Operator Sun Exploration & Production Company	8. Farm or Lease Name New Mexico BC State
3. Address of Operator P. O. Box 1861, Midland, Texas 79702	9. Well No. 1
4. Location of Well UNIT LETTER <u>F</u> <u>1980</u> FEET FROM THE <u>North</u> LINE AND <u>1980</u> FEET FROM THE <u>West</u> LINE, SECTION <u>23</u> TOWNSHIP <u>13-S</u> RANGE <u>32-E</u> NMPM.	10. Field and Pool, or Wildcat Baum Upper Pennsylvanian Undesignated
15. Elevation (Show whether DF, KT, GR, etc.) 4314.3' GR	12. County Lea

16. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:

PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>	CASING TEST AND CEMENT JOB <input checked="" type="checkbox"/>	

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

SPUD 2-9-84

R&C 11 JTS 13-3/8 655 STAG CS 442. 46002. 60W03 CMT. W/475 CAS CLEAN 2 1/2" SALT.
FP 200-700 CIRC 35 SXS WOC 12 HRS. TEST 13-3/8 TO 600 PSI. O.K.

2-16-84 - R&C 107 JTS 8-5/8 1000. 11400. 12061. 40W02 CMT. W/300 CAS CLEAN 2 1/2" SALT.
W/180 SALT, 1/4" FLUCEL. W/1/2" CAS. 1/2" SALT. 1/2" SALT. 1/2" SALT. 1/2" SALT.
CIRC 40 SXS. WOC 24 HRS. TEST 3/58 CSG TO 100 PSI, O.K.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED Eddie W. Seay TITLE Senior Accounting Asst. DATE 2-23-84

APPROVED BY Eddie W. Seay TITLE Oil & Gas Inspector DATE FEB 28 1984

CONDITIONS OF APPROVAL, IF ANY: