

Submit 3 Copies
to Appropriate
District Office

State of New Mexico
Energy, Minerals and Natural Resources Department

Form C-103
Revised 1-1-89

DISTRICT I
P.O. Box 1980, Hobbs, NM 88240

OIL CONSERVATION DIVISION
P.O. Box 2088
Santa Fe, New Mexico 87504-2088

DISTRICT II
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III
1000 Rio Brazos Rd., Aztec, NM 87410

WELL API NO.	30-25-28622
5. Indicate Type of Lease	STATE <input checked="" type="checkbox"/> FEE <input type="checkbox"/>
6. State Oil & Gas Lease No.	E-7353-2
7. Lease Name or Unit Agreement Name	
Saunders State	
8. Well No.	2
9. Pool name or Wildcat	Saunders Permo (Upper Penn)
10. Elevation (Show whether DF, RKB, RT, GR, etc.)	
4227.1 GR.	

SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)	
1. Type of Well: OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/>	
2. Name of Operator Eclipse Oil & Gas, Inc.	
3. Address of Operator P.O. Box 15122 Odessa, TX 79768	
4. Well Location Unit Letter E : 2310 Feet From The North Line and 990 Feet From The East Line Section 16 Township 14S Range 33E NMPM Lea County	
10. Elevation (Show whether DF, RKB, RT, GR, etc.) 4227.1 GR.	

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data	
NOTICE OF INTENTION TO:	SUBSEQUENT REPORT OF:
PERFORM REMEDIAL WORK <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>
OTHER: <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
	CASING TEST AND CEMENT JOB <input type="checkbox"/>
	OTHER: <input type="checkbox"/>

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

(NOTIFY CONSERVATION COMMISSION (505) 393-6161 24HRS. BEFORE OPERATIONS BEGIN)

- (1) MIRU Unit, test tbq. to 500#, lay down rods, POH w/tbg.
- (2) Set CIBP on WL @ 9700' and cap w/3sx. cmt. 35' w/ DUMP BAUER OR 25SX - TAG BOTTOM PLUG
- (3) TIH w/tbg. circ. hole w/10# BW w/25# SWG per bbl. Pump 25sx. plug @ 7000', FOH.
- (4) Stretch, cut and lay down 5 1/2" csg.
- (5) TIH w/tbg., Pump 50' in & 50' out plug across 5 1/2" stub. (TAG W/TBG.)
- (6) Pump 100' plug across 8-5/8" shoe @ 4206'. (TAG W/TBG.)
- (7) Pump 100' plug across 13-3/8" shoe @ 418'. (TAG W/TBG.)
- (8) Pump 15sx. surface plug.
- (9) Install dry hole marker.

NEED SALT PLUG F/1840' to 1740'

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Frelan Fields TITLE Agent DATE 9/19/00
(915) 366-1852
TELEPHONE NO.
TYPE OR PRINT NAME Frelan Fields

(This space for State Use)

APPROVED BY _____ TITLE _____ DATE _____

CONDITIONS OF APPROVAL, IF ANY: