

DISTRICT I
P.O. Box 1980, Hobbs, NM 88240

DISTRICT II
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III
1000 Rio Brazos Rd., Aztec, NM 87410

OIL CONSERVATION DIVISION
P.O. Box 2088
Santa Fe, New Mexico 87504-2088

ELL API NO.	30-25-28631
5. Indicate Type of Lease	STATE ☒ FEE ☐
6. State Oil & Gas Lease No.	E-7353-2
7. Lease Name or Unit Agreement Name	Saunders State
8. Well No.	3
9. Pool name or Wildcat	Saunders Permo (Upper Penn)

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well: OIL WELL ☒ GAS WELL ☐ OTHER ☐	2. Name of Operator Eclipse Oil & Gas, Inc.		
3. Address of Operator P.O. Box 15122 Odessa, TX 79768		4. Well Location Unit Letter <u>O</u> : <u>330</u> Feet From The <u>South</u> Line and <u>1650</u> Feet From The <u>East</u> Line Section <u>9</u> Township <u>14S</u> Range <u>33E</u> NMPM <u>Lea</u> County <u> </u>	
10. Elevation (Show whether DF, RKB, RT, GR, etc.) 4221 GR			

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data			
NOTICE OF INTENTION TO:		SUBSEQUENT REPORT OF:	
PERFORM REMEDIAL WORK ☐	PLUG AND ABANDON ☒	REMEDIAL WORK ☐	ALTERING CASING ☐
TEMPORARILY ABANDON ☐	CHANGE PLANS ☐	COMMENCE DRILLING OPNS. ☐	PLUG AND ABANDONMENT ☐
PULL OR ALTER CASING ☐	OTHER: ☐	CASING TEST AND CEMENT JOB ☐	OTHER: ☐

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.
(NOTIFY CONSERVATION COMMISSION (505)393-6161 24HRS BEFORE OPERATIONS BEGIN)

(1) MIRU Unit, test tbg. to 500#, lay down rods. POH w/tbg.
(2) Set CIBP on WL @ 9700' and cap w/25x cmt. 35' w/DUMP BAILER OR 25 SX SPOTTED w/TBG. - TAG
(3) TIH w/tbg. circ hole w/10# BW w/25# SWG per bbl., Pump 25sx. plug @ 7000' POH.
(4) Stretch cut and lay down 5 1/2" csg.
(5) TIH w/tbg. Pump 50' in & 50' out plug across 5 1/2" stub. (TAG W/TBG.)
(6) Pump 100' plug across 8-5/8" shoe @ 4200'. (TAG W/TBG.)
(7) Pump 100' plug across 13-3/8" shoe @ 435'. (TAG W/TBG.)
(8) Pump 15 sx. surface plug.
(9) Install dry hole marker.

→ SALT PLUG 1796' to 1696'

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Frelan Fields TITLE Agent DATE 9/19/00
TYPE OR PRINT NAME Frelan Fields (915) 366-1852
TELEPHONE NO.

This space for State Use)

APPROVED BY _____ TITLE ORIGINAL SIGNED BY DATE 9/19/00
CONDITIONS OF APPROVAL, IF ANY: COPY TO FIELD OFFICE