

STATE OF NEW MEXICO  
ENERGY AND MINERALS DEPARTMENT

OIL CONSERVATION DIVISION  
P.O. Box 2088  
SANTA FE, NEW MEXICO 87501

Form C-103  
Revised 10-1-78

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S	
LAND OFFICE	
OPERATOR	

5a. Indicate Type of Lease	
State <input checked="" type="checkbox"/>	Fee <input type="checkbox"/>

5. State Oil & Gas Lease No.

V-720

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT-" (FORM C-101) FOR SUCH PROPOSALS.)

XXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXX  
XXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXX  
XXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXX

1. OIL WELL ☒ GAS WELL ☐ OTHER ☐

7. Unit Agreement Name

2. Name of Operator  
Read & Stevens, Inc.

8. Farm or Lease Name  
Tres Papalotes

3. Address of Operator  
P.O. Box 1518, Roswell, NM 88201

9. Well No.

1

4. Location of Well

10. Field and Pool, or Wildcat

UNIT LETTER N 1980 FEET FROM THE West LINE AND 660 FEET FROM  
THE South LINE. SECTION 28 TOWNSHIP 14S RANGE 34E NMPM

Tres Papalotes

XXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXX  
XXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXX

5. Elevation(Show whether DF,RT,GR,etc.)

4123' GL

12. County  
Lea

XXXXXXXXXXXXXXXXXXXX  
XXXXXXXXXXXXXXXXXXXX

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data  
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:

PERFORM REMEDIAL WORK ☐  
TEMPORARILY ABANDON ☐  
PULL OR ALTER CASING ☐  
OTHER ☐

PLUG AND ABANDON ☐  
CHANGE PLANS ☐  
☐

REMEDIAL WORK ☐  
COMMENCE DRILLING OPNS. ☐  
CASING TEST AND CEMENT JOB ☐  
OTHER ☐

ALTERING CASING ☐  
PLUG AND ABANDONMENT ☐  
☒

Ran casing

X

Describe Proposed or Completed Operations(Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

5-20-84 Ran 159jts, 5 1/2"-17# N-80 & J-55, total 10,737', set @ 10,755', FC @ 10,712', set 140,000# on slips. Cmt w/550sx HLC, 475sx "H" 50/50 pozmix, .5% Halad-2C, 2% gel. Plug down @ 5:30pm 5-19-84, plug bumped @ 2250psi, float held. Release rig @ 11:00pm 5-19-84.

Ran csq as follows:

Float Shoe	1,65'
1jt 5 1/2"-17# N-80	39,48'
Float Collar	1,37'
65jts 5 1/2"-17# N-80	2712,95'
122jts 5 1/2"-17# J-55	4938,25'
71jts 5 1/2"-17# N-80	3043,30'
KB	18'
	10,755'

5-21-84 WOC 18hrs. Waiting to move rotary tools.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED B. Stubbs

TITLE Drilling & Production Manager

DATE 5-21-84

ORIGINAL SIGNED BY JERRY SEXTON

APPROVED BY DISTRICT 1 SUPERVISOR

TITLE

DATE

MAY 23 1984

CONDITIONS OF APPROVAL, IF ANY: