

OIL CONSERVATION DIVISION
P. O. BOX 2088
SANTA FE, NEW MEXICO 87501

Form C-103
Revised 10-1-76

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

5a. Indicate Type of Lease
State ☒ Fee ☐
5. State Oil & Gas Lease No.
B-9560

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR.
USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

OIL WELL ☒ GAS WELL ☐ OTHER- ☐

7. Unit Agreement Name
-
8. Farm or Lease Name NCT-1
New Mexico 'BG' State

9. Well No.
5

10. Field and Pool, or Wildcat
Saunders Permo
Upper Penn

UNIT LETTER N 660 FEET FROM THE South LINE AND 1680 FEET FROM
THE West LINE, SECTION 14 TOWNSHIP 14-S RANGE 33-E NMPM.

15. Elevation (Show whether DF, RT, GR, etc.)
4188' (GR)
12. County
Lea

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:

FORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
REPAIR OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>	CASING TEST AND CEMENT JOBS <input type="checkbox"/>	OTHER <u>Perforate + Complete</u> <input checked="" type="checkbox"/>

Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

TOTAL DEPTH 10,100'
PLUG BACK TOTAL DEPTH 10,095'
13 3/8" OD 54.5# J-55 CSG SET @ 525'
8 5/8" OD 24# J-55 CSG SET @ 4194'
5 1/2" OD 17# L-80 & K-55 CSG SET @ 10,100'

- PERFORATE 5 1/2" CSG W/2-JSPF FROM 9752' - 9758'; 9762' - 9766'; 9770' - 9776'; 9782' - 9785'; 9814' - 9818'; 9824' - 9827'; 9850' - 9872'; 9889' - 9894'; & 9916' - 9922'.
- SET RBP @ 10,000' AND PKR @ 9840'. ACIDIZE PERFS 9850' - 9922' W/4000 GALS 15% NE ACID AND 500# ROCK SALT.
- RESET RBP @ 9840' AND PKR @ 9700'. ACIDIZE PERFS 9752' - 9827' W/4000 GALS 15% NE ACID.
- RAN 2 7/8" TUBING AND SET @ 9945'.
- INSTALL PUMPING EQUIPMENT. TEST AND PLACE ON PRODUCTION.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED Jerry Sexton TITLE Asst Dist Supt. DATE 8-7-84

ORIGINAL SIGNED BY JERRY SEXTON
DISTRICT 1 SUPERVISOR

APPROVED BY _____ TITLE _____ DATE AUG - 9 1984

ADDITIONS OF APPROVAL, IF ANY:

RECEIVED

AUG - 8 1984

COMMUNICATIONS SECTION