Submit 3 Copies To Appropriate District State of New Mexico	F C 102
Office District I Largy, Minerals and Natural Resource	Form C-103 Revised March 25, 1999
1625 N. French Dr., Hobbs, NM 88240	WELL API NO.
District II 811 South First, Artesia, NM 88210 OIL CONSERVATION DIVISION	30-025-28817
District III 2040 South Pacheco	5. Indicate Type of Lease
1000 Rio Brazos Rd., Aztec, NM 87410 District IV Santa Fe, NM 87505	STATE X FEE
2040 South Pacheco, Santa Fe, NM 87505	6. State Oil & Gas Lease No. B-9505
SUNDRY NOTICES AND REPORTS ON WELLS	7. Lease Name or Unit Agreement No.
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLIG BACK TO A	- and a sum of our Astronactic Maine.
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)	New Mexico -AT- State
1. Type of Well:	New Mexico -Ai- State
Oil Well X Gas Well Other	
2. Name of Operator American Inland Resources Company, LLC.	8. Well No.
3. Address of Operator	9. Pool name or Wildcat
P.O. Box 50938	Saunders Permo Upper Penn
4. Well Location	-
Unit Letter E: 1980 feet from the North line and	660 West
Unit Letter feet from the line and feet from the line	
Section 15 Township 14-S Range 33-	E NMPM County Lea
10. Elevation (Show whether DR, RKB, RT, GR, etc.) 4212 GR	
11. Check Appropriate Box to Indicate Nature of Not	
NOTICE OF INTENTION TO: S PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORK	SUBSEQUENT REPORT OF:
REMEDIAL 1	WORK LI ALTERING CASING
TEMPORARILY ABANDON	DRILLING OPNS. PLUG AND
PULL OR ALTER CASING MULTIPLE CASING TES	ABANDONMENT L
COMPLETION CEMENT JO	
OTHER: Add nones to United.	
Add peris to wollcamp	
12. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion	
or recompilation.	stach wehoofe diagram of proposed completion
•	
Set CIBP above Penn perfs (± 9760'). Perf Wolfcamp from 9404' - 9747', acidize with	
9800 gal 15% NEFE. Run production equipment and return to producing from shut-in.	
Work to begin on or about 8-23-2000.	
•	
•	
• •	
	wledge and heliof
I hereby certify that the information above is true and complete to the best of my know	
I hereby certify that the information above is true and complete to the best of my known SIGNATURE Michael D. Puchael TITLE Operations	DATE 8-04-2000
I hereby certify that the information above is true and complete to the best of my known SIGNATURE Machael D. Prichard TITLE Operations Type or print name Michael D. Prichard	- E
I hereby certify that the information above is true and complete to the best of my known SIGNATURE Wichael D. Prichard TITLE Operations Type or print name Michael D. Prichard (This space for State use) OBIGINAL SIGNED BY CHRIS WILLIAMS	DATE 8-04-2000
I hereby certify that the information above is true and complete to the best of my known SIGNATURE Michael D. Prichard Type or print name Michael D. Prichard (This space for State use)	DATE 8-04-2000