

STATE OF NEW MEXICO  
ENERGY AND MINERALS DEPARTMENT

OIL CONSERVATION DIVISION  
P. O. BOX 2088  
SANTA FE, NEW MEXICO 87501

Form C-103  
Revised 10-1-78

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

5a. Indicate Type of Lease	
State <input checked="" type="checkbox"/>	Fee <input type="checkbox"/>
5. State Oil & Gas Lease No.	
LG 2414	

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)

1. <input checked="" type="checkbox"/> OIL WELL <input type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER-		7. Unit Agreement Name
2. Name of Operator Yates Petroleum Corporation		8. Farm or Lease Name Chalupa AAD State
3. Address of Operator 207 South 4th St., Artesia, NM 88210		9. Well No. 1
4. Location of Well UNIT LETTER <u>E</u> <u>2310</u> FEET FROM THE <u>North</u> LINE AND <u>330</u> FEET FROM THE <u>West</u> LINE, SECTION <u>13</u> TOWNSHIP <u>14S</u> RANGE <u>33E</u> NMPM.		10. Field and Pool, or Wildcat Saunders Permo Upper Perm
15. Elevation (Show whether DF, RT, GR, etc.) 4181.3' GR		12. County Lea

16. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data			
NOTICE OF INTENTION TO:		SUBSEQUENT REPORT OF:	
PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>	CASING TEST AND CEMENT JOBS <input type="checkbox"/>	OTHER <input checked="" type="checkbox"/> Acidize Well

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

12-6-84. POOH w/pump, rods and tubing.  
12-7-84. Swabbed well down to seating nipple.  
12-11-84. Acidized perforations 9821-9892' (via 2-7/8" tubing) with 10000 gals Westpad A, 25000 gals Series 72 type 20 acid and 15000 gals CO<sub>2</sub> in 2 equal stages. Ran 38 ball sealers between stages. Recovering load. Hung well on pump. Return well to production.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED <u>Juanita Goodlett</u>	TITLE <u>Production Supervisor</u>	DATE <u>12-12-84</u>
ORIGINAL SIGNED BY <u>JERRY SEXTON</u>		
APPROVED BY <u>DISTRICT 1 SUPERVISOR</u>	TITLE _____	DATE <u>DEC 17 1984</u>
CONDITIONS OF APPROVAL, IF ANY:		