

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

NEW MEXICO OIL CONSERVATION COMMISSION

Form C-103
Supersedes Old
C-102 and C-103
Effective 1-1-65

5a. Indicate Type of Lease
State <input type="checkbox"/> Fee <input checked="" type="checkbox"/>
5. State Oil & Gas Lease No.

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR.
USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/>	7. Unit Agreement Name
2. Name of Operator BTA Oil Producers	8. Farm or Lease Name Glad 7105 JV-D
3. Address of Operator 104 S. Pecos Midland Texas 79701	9. Well No. 1
4. Location of Well UNIT LETTER "G" 2086 FEET FROM THE North LINE AND 2086 FEET FROM THE East LINE, SECTION 26 TOWNSHIP 12-S RANGE 37-E NMPM.	10. Field and Pool, or Wildcat Gladiola, SW Devonian
15. Elevation (Show whether DF, RT, GR, etc.) 3881' G. L. 3892' K. B.	12. County Lea

16. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:		SUBSEQUENT REPORT OF:	
PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input checked="" type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>	CASING TEST AND CEMENT JOBS <input type="checkbox"/>	OTHER <input type="checkbox"/>

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

Plugging Procedure:

1/27/73 - Moved in Permian Basin Casing Pullers.
1/29 Layed down 203 jts of 2-3/8" tbg. Set CIBP @ 12,175' w/4 sx cmt. on top.
1/30 Shot 5-1/2" csg. @ 8993', 8422', 7952', 7486', 6968', 6500', 5995', 5724' & 5495'.
1/31 Shot 5-1/2" csg. @ 5216'.
2/01 Rec 5216' of 5-1/2" csg.
2/02 Set 50 sx cmt. @ 5216'; 50 sx @ 4485'.
2/03 Shot 8-5/8" csg @ 1480', 1399' & 1224'. Rec 1224' of 8-5/8" csg. Set 50 sx @ 1224'; 50 sx @ 440' & 10 sx @ surface.

Installed dry hole marker.

Final report.

PLUG AND ABANDON 2/3/73.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED <u>James Jones</u>	TITLE <u>Production Clerk</u>	DATE <u>Feb. 12, 1973</u>
APPROVED BY <u>John W. Rumpke</u>	TITLE <u>Geologist</u>	DATE <u>FEB 17</u>
CONDITIONS OF APPROVAL, IF ANY:		