

Submit 3 Copies  
to Appropriate  
District Office

State of New Mexico  
Energy, Minerals and Natural Resources Department

Form C-103  
Revised 1-1-89

DISTRICT I  
P.O. Box 1980, Hobbs, NM 88240

DISTRICT II  
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III  
1000 Rio Brazos Rd., Aztec, NM 87410

OIL CONSERVATION DIVISION  
P.O. Box 2088  
Santa Fe, New Mexico 87504-2088

WELL API NO. 30-025-28930
5. Indicate Type of Lease STATE <input checked="" type="checkbox"/> FEE <input type="checkbox"/>
6. State Oil & Gas Lease No. LG-2358
7. Lease Name or Unit Agreement Name Sunburst State
8. Well No. 1
9. Pool name or Wildcat Wildcat

SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)	
1. Type of Well: OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER	
2. Name of Operator Manzano Oil Corporation 505/623-1996	
3. Address of Operator P.O. Box 2107/Roswell, NM 88202-2107	
4. Well Location Unit Letter N : 660 Feet From The South Line and 1980 Feet From The West Line Section 11 Township 14 South Range 32 East NMPM Lea County	
10. Elevation (Show whether DF, RKB, RT, GR, etc.) 9750'	

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data	
NOTICE OF INTENTION TO:	SUBSEQUENT REPORT OF:
PERFORM REMEDIAL WORK <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>
OTHER: <input type="checkbox"/>	PLUG AND ABANDONMENT <input checked="" type="checkbox"/>
	CASING TEST AND CEMENT JOB <input type="checkbox"/>
	OTHER: <input type="checkbox"/>

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

5/19/93 Set CIBP @ 8890'. Put 5 sx cmt 50' on plug.  
5/20/93 RIH w/2-7/8" tbg to 8840'. Displaced hole w/9.5# mud.  
5/21/93 Cut csg @ 5350'. Pulled on csg. Would not move. Pumped 25 sx plug from 5400' to 5150'.  
5/22/93 Cut csg @ 3740'. Csg came free.  
5/25/93 RIH w/2-7/8" tbg to 4166'. Pump 60 sx cement plug. PU. WOC. RIH. Tagged cmt @ 3669'. PU to 1690'. Pump 60 sx cmt plug from 1690' to 1598'. Cut off wellhead. Set 10 sx 38' cmt surface plug. Install dry hole marker. Cleaned location. Ready for inspection.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Allison Raney TITLE Engineering Technician DATE 6/3/93  
TYPE OR PRINT NAME Allison Raney TELEPHONE NO. 623-1996

(This space for State Use)

APPROVED BY Jack Griffin TITLE OIL & GAS INSPECTOR DATE SEP 07 1993  
CONDITIONS OF APPROVAL, IF ANY:

1. FLORENCE BERRY

JUN 04 1993  
OLD HOBBS OFFICE