

OIL CONSERVATION DIVISION

P. O. BOX 2088  
SANTA FE, NEW MEXICO 87501

Form C-103  
Revised 10-1-73

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

5a. Indicate Type of Lease	
State <input type="checkbox"/>	Fee <input checked="" type="checkbox"/>
5. State Oil & Gas Lease No.	

SUNDRY NOTICES AND REPORTS ON WELLS  
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR.  
USE APPLICATION FOR PERMIT L-1 (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL <input type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER- P&A		7. Unit Agreement Name
2. Name of Operator Yates Petroleum Corporation		8. Farm or Lease Name Woodward ABD
3. Address of Operator 207 South 4th St., Artesia, NM 88210		9. Well No. 1
4. Location of Well UNIT LETTER G, 1980 FEET FROM THE North LINE AND 1980 FEET FROM THE East LINE, SECTION 24 TOWNSHIP 14S RANGE 35E NMPM.		10. Field and Pool, or wildcat Austin-Permo Upper Penn
11. Elevation (Show whether DF, RT, GR, etc.) 3983.9' GR		12. County Lea

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data  
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:

PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPMS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input checked="" type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>	CASING TEST AND CEMENT JOBS <input type="checkbox"/>	OTHER <input type="checkbox"/>

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

12-2-85. Rigged up pulling unit. Pull production equipment.  
12-3-85. Set CIBP at 10275' w/35' cement on top.  
12-4-85. Cut 5-1/2" casing at 8250'. Could not pull. Cut 5-1/2" at 8050'. Could not pull. Cut 5-1/2" casing at 7062'. Could not pull. Rigged up casing jacks and pulled casing from slips. Pulled 114 joints 5-1/2" casing.  
12-6-85. Plugged well as follows:  
Plug #1: 8250-8000' w/35 sacks Class "C" with 2% CaCl<sub>2</sub>. WOC 2 hrs. Tagged cement @8010'.  
Plug #2: 7112-7012' w/50 sacks Class "C".  
Plug #3: 6180-6080' w/50 sacks Class "C" w/2% CaCl<sub>2</sub>.  
Plug #4: 4672-4572' w/50 sacks Class "C" w/2% CaCl<sub>2</sub>. Tagged cement at 4520'.  
Plug #5: 2100-2000' w/50 sacks Class "C".  
Plug #6: Surface w/20 sacks Class "C".  
Set regulation abandonment marker.  
Well plugged and abandoned 12-7-85.

Verbal approval for plugging procedure given by Mr. Eddie Seay, NMOCD, Hobbs, on 11-12-85, to Mr. Ray Stall, Yates Petroleum.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED <u>[Signature]</u>	TITLE <u>Production Supervisor</u>	DATE <u>12-12-85</u>
APPROVED BY <u>[Signature]</u>	TITLE <u>OIL &amp; GAS INSPECTOR</u>	DATE <u>APR 7 1987</u>
CONDITIONS OF APPROVAL, IF ANY:		