

Submit 3 Copies
to Appropriate
District Office

State of New Mexico
Energy, Minerals and Natural Resources Department

Form C-103
Revised 1-1-89

DISTRICT I
P.O. Box 1980, Hobbs, NM 88240

DISTRICT II
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III
1000 Rio Brazos Rd., Aztec, NM 87410

OIL CONSERVATION DIVISION

P.O. Box 2088
Santa Fe, New Mexico 87504-2088

WELL API NO.	30-025-28996
5. Indicate Type of Lease	STATE <input type="checkbox"/> FEE <input checked="" type="checkbox"/>
6. State Oil & Gas Lease No.	
7. Lease Name or Unit Agreement Name	LOWE LAND COMPANY
8. Well No.	1
9. Pool name or Wildcat	KING (DEVONIAN), NORTH
10. Elevation (Show whether DF, RKB, RT, GR, etc.)	
3890.3 GR	

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT"
(FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well: OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/>	2. Name of Operator ECHO PRODUCTION, INC.
3. Address of Operator P.O. BOX 1210 GRAHAM, TX 76450	

4. Well Location Unit Letter C : 330 Feet From The NORTH Line and 2310 Feet From The WEST Line	Section 3 Township 13S Range 37E NMPM LEA County
---	--

10. Elevation (Show whether DF, RKB, RT, GR, etc.)	3890.3 GR
--	-----------

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data	
NOTICE OF INTENTION TO:	SUBSEQUENT REPORT OF:
PERFORM REMEDIAL WORK <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>
OTHER: <input type="checkbox"/>	PLUG AND ABANDONMENT <input checked="" type="checkbox"/>
	CASING TEST AND CEMENT JOB <input type="checkbox"/>
	OTHER: <input type="checkbox"/>

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

SET CIBP @ 11,475'. DUMPED 4 SACKS OF CMT ON PLUG. SPOT 25 SACK PLUG @ 8900'.
SPOTTED 35 SACK PLUG @ 7086.11 - TAGGED UP ON 35 SACK PLUG @ 7086'. TOP OF FILL
@ 6960'. SPOTTED 60 SACK PLUG @ 4632'. PULLED TUBING TO 2209' AND PUMPED 35 SACK
PLUG. PULLED TUBING OUT OF HOLE. PUT 10 SACK PLUG AT SURFACE. CUT 8 5/8" AND STARTING
HEAD OFF. PUT PLATE ON 12 3/4" PIPE. PUT UP MARKER ON 1/4/95.

JERRY FROM HOBBS OFFICE OKAYED PLUGS. HE WAS THERE TO WITNESS.

COPY OF COMPLETE PROCEDURE ATTACHED.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Ronda Wellman TITLE PRODUCTION AGENT DATE 1/9/95

TYPE OR PRINT NAME RONDA WELLMAN TELEPHONE NO. 817-549-3292

(This space for State Use)

APPROVED BY Hayden W. Winters TITLE FIELD REPRESENTATIVE II DATE MAR 06 1995

CONDITIONS OF APPROVAL, IF ANY: