

STATE OF NEW MEXICO
ENERGY AND MINERALS DEPARTMENT

OIL CONSERVATION DIVISION
P. O. BOX 2088
SANTA FE, NEW MEXICO 87501

Form C-103
Revised 10-1-78

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

5a. Indicate Type of Lease	
- State <input checked="" type="checkbox"/>	Fee <input type="checkbox"/>
5. State Oil & Gas Lease No. V-1178	

SUNDRY NOTICES AND REPORTS ON WELLS <small>(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)</small>	
1. <input type="checkbox"/> OIL WELL <input type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER- Dry	7. Unit Agreement Name
2. Name of Operator Exxon Corporation	8. Form or Lease Name New Mexico EN State
3. Address of Operator Box 1600, Midland, Texas 79702	9. Well No. 1
4. Location of Well UNIT LETTER I, 1980 FEET FROM THE South LINE AND 660 FEET FROM East LINE, SECTION 21 TOWNSHIP 13S RANGE 33E NMPM.	10. Field and Pool, or Wildcat Lazy J Pennsylvanian
15. Elevation (Show whether DF, RT, GR, etc.) KB 4258 GL 4246	12. County Lea

10. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data			
NOTICE OF INTENTION TO:		SUBSEQUENT REPORT OF:	
PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPER. <input type="checkbox"/>	PLUG AND ABANDONMENT <input checked="" type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>	CASING TEST AND CEMENT JOBS <input type="checkbox"/>	OTHER <input type="checkbox"/>

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

The above well was plugged and abandoned as follows:

Set CIBP at 9406 w/25 sx cmt.
Set plug 6000-5700' W/25 sx C1C.
Cut casing at 4700'.
Set plugs 4750-4640 w/25 sx C1C
4038-3850 w/40 sx C1C
1500- 1380 W/40 sx C1C
506-386 w/40 sx C1C and
50'-surface w/ 25 sx.

P & A'd 12-18-85.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED <u>Melba Knippling</u>	TITLE <u>Section Head</u>	DATE <u>1-10-86</u>
APPROVED BY <u>Lyle F. Turnacliff</u>	TITLE <u>OIL & GAS INSPECTOR</u>	DATE <u>MAR 8 5 1986</u>
CONDITIONS OF APPROVAL, IF ANY:		

RECEIVED
JAN 15 1986
C-3
HOBBS OFFICE