

STATE OF NEW MEXICO  
ENERGY AND MINERALS DEPARTMENT

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.O.S.	
LAND OFFICE	
OPERATOR	

OIL CONSERVATION DIVISION  
P. O. BOX 2088  
SANTA FE, NEW MEXICO 87501

Form C-103  
Revised 10-1-78

5a. Indicate Type of Lease State <input checked="" type="checkbox"/> Fee <input type="checkbox"/>
5. State Oil & Gas Lease No. V-1178

**SUNDRY NOTICES AND REPORTS ON WELLS**  
DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR.  
USE "APPLICATION FOR PERMIT - " (FORM C-101) FOR SUCH PROPOSALS.)

1. <input type="checkbox"/> OIL WELL <input type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER- Dry	7. Unit Agreement Name
2. Name of Operator Exxon Corporation	8. Farm or Lease Name New Mexico EN State
3. Address of Operator Box 1600, Midland, Texas 79702	9. Well No. 1
4. Location of Well UNIT LETTER I, 1980 FEET FROM THE South LINE AND 660 FEET FROM THE East LINE, SECTION 21 TOWNSHIP 13S RANGE 33E NMPM.	10. Field and Pool, or Wildcat Lazy J Pennsylvanian
11. Elevation (Show whether DF, RT, GR, etc.) KB 4258 GL 4246	12. County Lea

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data  
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:

PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input checked="" type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPER. <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>	CASING TEST AND CEMENT JOBS <input type="checkbox"/>	

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1102.

The above well will be plugged and abandoned as follows:  
Set CIBP at 9406 w/25 sx cmt.  
Set plug 6000-5700' W/25 sx C1C.  
Cut csg. at freepoint - approximately 4700'.  
Set plugs 4750-4640 w/25 sx C1C  
4038-3850 w/40 sx C1C  
1500- 1380 w/40 sx C1C  
506-386 w/40 sx C1C and  
50'-surface w/ 25 sx..

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED <u>Melba Knippling</u>	TITLE <u>Section Head</u>	DATE <u>1-10-86</u>
ORIGINAL SIGNED BY JERRY SEXTON DISTRICT 1 SUPERVISOR		
APPROVED BY <u></u>	TITLE <u></u>	DATE <u>JAN 16 1986</u>

CONDITIONS OF APPROVAL, IF ANY:

RECEIVED  
JAN 15 1986  
O.C.D.  
HOBBS OFFICE