Submit 3 Copies to Appropriate	State of New Me Energy, Minc and Natural Re		Form C·103 Revised 1·1-89
District Office		NDIVICION	
<u>DISTRICT I</u> P.O. Box 1980, Hobbs, NM 88240	OIL CONSERVATIO P.O. Box 208		WELL API NO.
DISTRICT II P.O. Drawer DD, Antesia, NM 88210	30-025-29081 5. Indicate Type of Lease STATE X FEE		
DISTRICT III 1000 Rio Brazos Rd., Aztec, NM 87410			6. State Oil & Gas Lease No. LG-3818
SUNDRY NO (DO NOT USE THIS FORM FOR PR DIFFERENT RESI	7. Lease Name or Unit Agreement Name		
(FORM	C-101) FOR SUCH PROPOSALS.)		-
1. Type of Well: OIL WELL XX WELL AAS WELL	Pyro ABK State		
 Name of Operator YATES PETROLEUM CORPO 	8. Well No.		
3. Address of Operator	9. Pool name or Wildcat		
105 South 4th St., Ar	Lazy J Penn		
4. Well Location Unit Letter B:66	50 Feet From The North	Line and19	80 Feet From The East Line
Section 33	Township 13S Ra	inge 33E	NMPM Lea County
	10. Elevation (Show whether	DF, RKB, RT, GR, etc.)	
		43.5' GR	Concert on Other Date
	Appropriate Box to Indicate		SEQUENT REPORT OF:
NOTICE OF IN	NTENTION TO:	506	
		REMEDIAL WORK	
	IG OPNS.		
OTHER:	·		
12. Describe Proposed or Completed Op	erations (Clearly state all pertinent details, a		uding estimated date of starting any proposed
6878'. Second stag	cemented in two stages. ge did not circulate, bu Propose to plug and aba	t cement bond 1	ulated cement at DV tool at og still showing bond when ::
9550'. Tag pl	ug.		g (35 sack minimum) up to
3. Pull up and spe	25#/barrel salt gel mud ot cement plug from 7900 Abo top at 7647'. Tag	-7600' to cover	: 4-1/2" scab lines from
			top of Glorieta at 5467'.
5. Pull up and sp	ot cement plug from 4250	-4100' to cover	: 8-5/8" shoe at 4195'.
6. Pull up and sp	ot cement plug from 1725	-1600' to cover	Anhydrite at 1668'.
7. Perforate at 4	50'. Pump down 5-1/2" c	asing and cemen	CONTINUED NEXT PAGE
I hereby certify that the information above is	true and complete to the best of my knowledge an	d belief.	· ·
SIGNATURE AUSTRALIA	In T	me Production	<u>Clerk</u> DATE May 19, 1993
TYPE OR PRINT NAME Rusty	Klein		теlерноне но. 505/748-
(This space for State USRIGINAL SIG			MAY 21 199
APPROVED BY		m.e	DATE
CONDITIONS OF APPROVAL, IF ANY:			
APPROVED BY		T.E	DATE

RECEIVED

MAY 2 0 1993

OCD HOBBS OFFICE

		• -	~	
Submit 3 Copies lo Appropriate District Office	State of New Me Energy, Mincs and Natural Re			Form C-103 Revised 1-1-89
DISTRICT I P.O. Box 1980, Hobbs, NM 88240	OIL CONSERVATIO P.O. Box 208		WELL API NO.	
DISTRICT II P.O. Drawer DD, Artesia, NM 88210	Santa Fe, New Mexico		30-025-290 5. Indicate Type of Lease	·
DISTRICT III 1000 Rio Brazos Rd., Aztec, NM 87410			6. State Oil & Gas Lease No LG-3818	··· •
	INFO AND DEPORTS ON WEL			
(DO NOT USE THIS FORM FOR PR DIFFERENT RESE	ICES AND REPORTS ON WEL OPOSALS TO DRILL OR TO DEEPEN RVOIR. USE "APPLICATION FOR PER >-101) FOR SUCH PROPOSALS.)	OR PLUG BACK TO A	7. Lease Name or Unit Agree	ement Name
1. Type of Well: OIL GAS				
WELL X WELL	OTHER		Pyro ABK Sta	te
2. Name of Operator YATES PETROLEUM CORPOR	ͻ៱ͲϒϴΝ		8. Well No.	
3. Address of Operator			9. Pool name or Wildcat	
105 South 4th St., Art	tesia, NM 88210		Lazy J. Penn	
4. Well Location				
	0 Feet From The North	Line and198		East Line
Section 33	Township 13S Ra	nge	NMPM 33E	County
	10. Elevation (Show whether 4243.5			
··· Chaole	Appropriate Box to Indicate 1		enort or Other Data	
II. Check NOTICE OF IN			SEQUENT REPOR	RT OF:
		REMEDIAL WORK	ALTERI	
	CHANGE PLANS		G OPNS. 📃 PLUG A	
		CASING TEST AND C		
OTHER:		OTHER:	·	
 Describe Proposed or Completed Oper work) SEE RULE 1103. 	rations (Clearly state all pertinent details, an	nd give pertinent dates, inclu	uding estimated date of starting	лту proposed
CONTINUED FROM PAGE	1.			
CONTINUED FROM TAGE	1.			
with 75 sacks.	Leave 100' cement plug lug at surface. Instal			
with 75 sacks. 8. Set at 15 sack p	Leave 100' cement plug	l regulation ab	oandonment marker.	
with 75 sacks. 8. Set at 15 sack p	Leave 100' cement plug lug at surface. Instal	l regulation ab	oandonment marker.	
with 75 sacks. 8. Set at 15 sack p	Leave 100' cement plug lug at surface. Instal	l regulation ab	oandonment marker.	
with 75 sacks. 8. Set at 15 sack p NOTE: NOTIFY NMOCD	Leave 100' cement plug olug at surface. Instal - HOBBS (393-6161) 24 H	l regulation ab OURS PRIOR TO C Ibelief.	andonment marker.	G OPERATIONS.
with 75 sacks. 8. Set at 15 sack p NOTE: NOTIFY NMOCD	Leave 100' cement plug olug at surface. Instal - HOBBS (393-6161) 24 H	l regulation ab OURS PRIOR TO C Ibelief.	oandonment marker.	G OPERATIONS.
with 75 sacks. 8. Set at 15 sack p NOTE: NOTIFY NMOCD	Leave 100' cement plug olug at surface. Instal - HOBBS (393-6161) 24 H	l regulation ab OURS PRIOR TO C Ibelief.	Clerk	G OPERATIONS.
with 75 sacks. 8. Set at 15 sack p NOTE: NOTIFY NMOCD	Leave 100' cement plug olug at surface. Instal - HOBBS (393-6161) 24 H	l regulation ab OURS PRIOR TO C Ibelief.	Clerk	G OPERATIONS.
with 75 sacks. 8. Set at 15 sack p NOTE: NOTIFY NMOCD I hereby certify that the information above if the SIONATURE Human TYPE OR PRINT NAME Rusty	Leave 100' cement plug olug at surface. Instal - HOBBS (393-6161) 24 H	l regulation ab OURS PRIOR TO C Ibelief. ne Production	Clerk	G OPERATIONS.

OCD HOBPS OFFICE

TAY 2 0 1993

RECEIVED

.