

STATE OF NEW MEXICO
ENERGY AND MINERALS DEPARTMENT

OIL CONSERVATION DIVISION

P. O. BOX 2088
SANTA FE, NEW MEXICO 87501

Form C-103
Revised 10-1-78

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATION	

5a. Indicate Type of Lease	
State <input checked="" type="checkbox"/>	Fee <input type="checkbox"/>
5. State Oil & Gas Lease No.	
LG 3818	
7. Unit Agreement Name	
8. Farm or Lease Name	
Pyro ABK State	
9. Well No.	
1	
10. Field and Pool, or wildcat	
Lazy J Penn	
12. County	
Lea	

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE APPLICATION FOR PERMIT TO DRILL FORM C-101 FOR SUCH PROPOSALS.)

OIL WELL <input checked="" type="checkbox"/>	GAS WELL <input type="checkbox"/>	OTHER <input type="checkbox"/>
Name of Operator		
Yates Petroleum Corporation		
Address of Operator		
207 South 4th St., Artesia, NM 88210		
Location of Well		
UNIT LETTER	B	660 FEET FROM THE North LINE AND 1980 FEET FROM
THE East	33	TOWNSHIP 13S RANGE 33E N.M.P.M.

11. Elevation (Show whether DF, RT, GR, etc.)
4243.5' GR

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data			
NOTICE OF INTENTION TO:		SUBSEQUENT REPORT OF:	
PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPER. <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>	CASING TEST AND CEMENT JOBS <input type="checkbox"/>	OTHER <input checked="" type="checkbox"/> Returned Well to Production

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1503.

Fishing on well 9-20-85 - 12-23-85.

12-15-85. WIH w/overshot, jars and tubing. Caught fish at 9676'. Tried to unset anchor. Pulled loose from anchor. TOOHH with tubing, overshot and jars. WIH w/cutrite shoe, dress-off mill and tubing to 9752'. Dressed off tubing to 9753'. TOOHH w/shoe, mill and tubing. WIH with overshot, jars, collars and tubing to 9753'. Caught fish. Jarred on fish. Overshot came loose. Could not catch fish again. COOH with overshot and tubing. WIH with cutrite shoe, washpipe and tubing to 9755'. Washed over anchor. Pushed anchor to 9806'. TOOHH with shoe, washpipe and tubing. RU wireline and tagged anchor at 9844'. WIH with bit, collars and 4-3/4" string mill and tubing. Cleaned out bad spot at 7850' to 7920'. TOOHH. WIH with CIBP and set at 8258'. Set 4-1/2" guide shoe at 8074', 1 jts 4-1/2" 13.5# P-110 flush joint casing, 4-1/2" landing collars, 8 jts 4-1/2" 13.5# P-110 casing, liner hanger and 2-7/8" tubing. Top of liner 7700'. Cemented liner with 50 sx Class H w/.5% CF-14 + .4% TF-4. Stung out of liner. Tagged cement at 7680'. Drilled cement and liner hanger at 7700'. WIH to 8032'. Drilled out landing collar, cement and shoe to 8074'. WIH to 8257'. Drilled out CIBP. WIH to 9840'. TOOHH with bit, collars and tubing.

12-23-85. Set pumping equipment. Returned well to production.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief

SIGNED <u>Eddie W. Sedy</u>	TITLE <u>Production Supervisor</u>	DATE <u>1-8-86</u>
APPROVED BY <u>Eddie W. Sedy</u>	TITLE <u>Oil & Gas Inspector</u>	DATE <u>JAN 10 1986</u>

RECEIVED

JAN 10 1986

O.C.D.
HONORARY OFFICE