

STATE OF NEW MEXICO
ENERGY AND MINERALS DEPARTMENT

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

OIL CONSERVATION DIVISION
P. O. BOX 2088
SANTA FE, NEW MEXICO 87501

Form C-103
Revised 10-1-79

5a. Indicate Type of Lease
State ☒ Fee ☐
5. State Oil & Gas Lease No.
LG 2612

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR.
USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

1. <input checked="" type="checkbox"/> OIL WELL <input type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER-		7. Unit Agreement Name
2. Name of Operator MWJ PRODUCING COMPANY		8. Farm or Lease Name Saunders 10 State
3. Address of Operator 1804 First National Bank Bldg Midland, Texas 70701		9. Well No. 3
4. Location of Well UNIT LETTER <u>D</u> <u>660</u> FEET FROM THE <u>North</u> LINE AND <u>660</u> FEET FROM <u>West</u> LINE, SECTION <u>10</u> TOWNSHIP <u>14S</u> RANGE <u>33E</u> NMPM.		10. Field and Pool, or Wildcat Saunders Permo Upper Pen
15. Elevation (Show whether DF, RT, GR, etc.) 4221.7' GL		12. County Lea

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:

SUBSEQUENT REPORT OF:

PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input checked="" type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>	CASING TEST AND CEMENT JOB <input checked="" type="checkbox"/>	OTHER <input type="checkbox"/>

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

9/4/85: Spud 17-1/2" hole @ 7:30 PM. (MI & RU Tri-Service Rig #2)
9/5/85: Ran 11 jts 13-3/8" csg & set @ 410'. Cmt'd w/450 sx Class "C" w/4% CaCl. Circ'd approx 60 sx. (wt of csg 61#). NU BOP & tstd to 1000 psi for 30 min, OK.
9/11/85: Ran 101 jts 8-5/8" 28# & 32# 8-5/8" csg & set @ 4142'. Cmt'd w/1300 sx Howco Lite w/15# salt, 5# gilsonite & 1/4# flocele followed by 200 sx Class "C" w/2% CaCl. Circ'd 25 sx. NU BOP & tstd to 1500 psi. WOC 18 hrs.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED Pat Drexler TITLE Pat Drexler - Agent DATE 9/13/85

ORIGINAL SIGNED BY JERRY SEXTON

APPROVED BY DISTRICT 1 SUPERVISOR

TITLE _____

DATE SEP 17 1985

CONDITIONS OF APPROVAL, IF ANY:

RECEIVED

SEP 16 1985

U.S. AIR FORCE