

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

5a. Indicate Type of Lease	
State <input checked="" type="checkbox"/>	Fee <input type="checkbox"/>
5. State Oil & Gas Lease No.	
V-648	

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/>		7. Unit Agreement Name
2. Name of Operator J. M. Huber Corporation		8. Farm or Lease Name Fort Ranch State
3. Address of Operator 7120 I-40 West, Suite 232, Amarillo, Texas 79106		9. Well No. 1
4. Location of Well UNIT LETTER <u>P</u> , <u>330</u> FEET FROM THE <u>south</u> LINE AND <u>600</u> FEET FROM THE <u>east</u> LINE, SECTION <u>11</u> TOWNSHIP <u>14S</u> RANGE <u>33E</u> NMPM.		10. Field and Pool, or WHdcat Saunders U. Permo-Penn
15. Elevation (Show whether DF, RT, GR, etc.) KB 4206'		12. County Lea

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:

PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>	CASING TEST AND CEMENT JOBS <input type="checkbox"/>	OTHER Tank battery hit by lightning <input checked="" type="checkbox"/>

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1403.

The Fort Ranch State tank battery was hit by lightning at approximately 6:30 p.m. 6-1-87. A 500 bbl fiberglass water storage tank and a 500 bbl steel oil tank were severely damaged and were replaced with two 500 bbl steel tanks. No leakage of oil or water occurred.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief. 806/353-9837

SIGNED Robert R. Glenn TITLE District Production Manager DATE 6-3-87

Orig. Signed by
Paul Kautz
Geologist

APPROVED BY _____ TITLE _____ DATE JUN 11 1987

CONDITIONS OF APPROVAL, IF ANY: