STATE OF NEW MEXICO ENERGY AND MINERALS DEPARTMENT

HO. OF COPIES HESELVED	
DISTRIBUTION	
SANT/ FL	
FILE	
U.S.O.S.	
LAND OFFICE	
OPEMATOR	

OIL CONSERVATION DIVISION P. O. BOX 2088

		1,		
	1	500	19-1	-18

SANT/ FL	SANTA FE,	NEW MEXICO 87501	19-1-7
FILE			5a. Indicate Type of these
U.S.a.S.		•	State The X
LAND OFFICE			5. State Off & Got Care No.
OPENATOR			
SI	INDRY NOTICES AND REPORT	TS ON WELLS	
(no hot use this fond f	JNDRY NOTICES AND REPORT OR PROPOSALS TO DRILL OR TO DELPEN OR PLICATION FOR PERMIT -" (FORM C-101)	PLUG BACK TO A DIFFERENT RESERVOIR, FOR SUCH PROPOSALS.)	
i.			7. Unit Agreement Lame
MELL XX MELL GAS	OTHER-		
2. Name of Operator			8. Farm of Leane Name
Gary L. Benne	Pearl Western		
3. Address of Operator	9 1 . 4	-	9. Well No.
P.O. Box 168	44 Lulbock	TX 19490	1-Y
4. Location of Well			10. Field and Pool, or Wildeat
L L	1980 Sou	ith 610	Gladiola, Wolfgamp
THE West LINE.	SECTION 18 TOWNSHIP	12 S MANGE 38 E	HMPM.
	15. Elevation (Show i	whether DF, RT, GR, etc.)	12. County
	3001	.6 DF	Lea
Ch	eck Appropriate Box To India	cate Nature of Notice, Report	or Other Data
	OF INTENTION TO:		QUENT REPORT OF:
·			
PERFORM REMEDIAL WORK	PLUG AND ABAND	ON X REMEDIAL WORK	ALTERING CASING
TEMPORARILY ABANDON		COMMENCE DRILLING OPHS.	PLUG AND AFARDORPH NT
PULL OR ALTER CABING	CHANGE PLANS	CASING TEST AND CEMENT JOB	
		OTHER	
01HEP			
	Carely and Clearly state all nexts	ant details, and sine parties at date in	neluding estimated date of starting any proposed
innih) see nule 1103.	ted Operations (Credity State att pertin	ient neturis, unu give pertinent autes, ti	nethating excenting united of starting any proposed
)', Squeezed Perforat	
5 1/2" casin	g set @ 9700', PBTD	@ 9680', TOC @ 6400)', 8 5/8" @ 4445'
Propose to c	ut off casing @ 6300)' and salvage. Place	e cement plugs from
PBTD of 9680	' to 9400' to comple	etely cover Wolfcamp	Formation. Place a
20 SX plug a	cross the cut-off ca	sing stub @ 6300'. F	Place a 10 SX plug
		ce casing located @ 4	
		e. Place last plug @	
Install bly	noie Marker & Clean	Location. Use Drilli	ng mud between Plugs.
011 011	ICS MUST RE	min 0 = 100 0	·
Bettom	PLUE PHT-0	RE PINC & SUM	E PLUC MUST BE
TR66ED	10 , 0 41 0	TEGE F SAU	E PLUC Mas.
		The same	
100 014	6 DT 1000.	THE COMMISSION MUST BE A	NOTIFIED 24
, - 0 , 0 4	<u>-</u> . •	THE PROPERTY OF THE PROPERTY O	LILILLO
•		TO CHOING OF EXALIONS FOR	THE C-103
		TO BE APPROVED.	-
The same of the sa	metion above is true and complete to the	he heat of my knowledge and halist	
18. I hereby certify that the infor-	mation above is true and complete to th	ir best of my knowledge and bellef.	
		Engineer	: 5/16/00

DISTRICT 1 SUPERVISOR

.MAY 1 8 1988