

Submit 3 Copies
to Appropriate
District Office

State of New Mexico
Energy, Minerals and Natural Resources Department

Form C-103
Revised 1-1-89

DISTRICT I
P.O. Box 1980, Hobbs, NM 88240

DISTRICT II
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III
1000 Rio Brazos Rd., Aztec, NM 87410

OIL CONSERVATION DIVISION
P.O. Box 2088
Santa Fe, New Mexico 87504-2088

WELL API NO.	30-025-29421
5. Indicate Type of Lease	STATE ☐ FEE ☒
6. State Oil & Gas Lease No.	
7. Lease Name or Unit Agreement Name	
Elkan A	
8. Well No.	1
9. Pool name or Wildcat	Alston Ranch Upper Penn
10. Elevation (Show whether DF, RKB, RT, GR, etc.)	
4110.5'	

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT"
(FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well:	OIL WELL ☒ GAS WELL ☐ OTHER ☐
2. Name of Operator	OXY USA Inc.
3. Address of Operator	P.O. Box 50250 Midland, TX. 79710
4. Well Location	Unit Letter <u>L</u> : <u>1650</u> Feet From The <u>South</u> Line and <u>990</u> Feet From The <u>West</u> Line
Section <u>25</u>	Township <u>13S</u> Range <u>34E</u> NMPM Lea County
10. Elevation (Show whether DF, RKB, RT, GR, etc.)	
4110.5'	

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data	
NOTICE OF INTENTION TO:	SUBSEQUENT REPORT OF:
PERFORM REMEDIAL WORK ☐	REMEDIAL WORK ☐
TEMPORARILY ABANDON ☐	ALTERING CASING ☐
PULL OR ALTER CASING ☐	COMMENCE DRILLING OPNS. ☐
OTHER: ☐	PLUG AND ABANDONMENT ☒
	CASING TEST AND CEMENT JOB ☐
	OTHER: Unsuccessful recompletion ☒

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

TD - 10800' Penn Perfs 10368'-10518' Wolfcamp Perfs - 9495'-9507'

This well was Plugged & Abandoned in the following manner:

See other side

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE David Stewart TITLE Production Accountant DATE 7/25/91
TYPE OR PRINT NAME David Stewart TELEPHONE NO. 9156855717

(This space for State Use)

APPROVED BY Cory A. Sil TITLE INSPECTOR DATE OCT 23 1991
CONDITIONS OF APPROVAL, IF ANY:

Attachment C-103
OXY USA Inc.
Elkan A #1
Sec 25 T13S R34E
Lea County, New Mexico

4/26/91 - 5/6/91

MIRU PU, POOH w/ rods & pump, NDWH NU BOP, POOH w/ 2 7/8" tbg, CO to 10800'. RIH & set 5 1/2 CIBP @ 10260', plugging off Penn perfs 10368-10518', test to 500#, held OK, dump 4sx (34') cmt on top, PBTD-10226'. Perf Wolfcamp w/ 2SPF @ 9495,96,97,98,99,9500,01,-02,03,04,05,06,9507', total 26 holes. SITP-125#, acidize Wolfcamp perfs 9495-9507' w/ 5000 gal 15% NeFE HCl acid. Swab trace of oil & 56BLW. SITP-325#, swab trace of oil & 72BLW in 9 1/2 hrs. SITP-130#, swab trace of oil, 8BLW, 11BW in 5 1/2 hrs. RIH & set 5 1/2 CIBP @ 9445', plugging off Wolfcamp perfs 9495-9507', dump 4sx (34') cmt on top, PBTD-9411'. POOH w/ tbg, RDPU, WO approval to P&A.

7/10/91

Notify NMOCD, MIRU PU, RIH w/ tbg, tag cmt @ 9410', circ hole w/ mud laden fluid, POOH w/ tbg. RIH w/ free point, RU wireline, cut 5 1/2 csg @ 6997'. POOH w/ 165 jts 5 1/2 csg. RIH w/ tbg, tag csg sub @ 6997', RIH to 7047', set 100' cmt plug w/ 25sx Cl H cmt, WOC. RIH & tag cmt plug @ 6948'. POOH to 5800', set 100' cmt plug across Glorieta 5800-5700' w/ 35sx Cl H cmt, WOC. POOH to 4350', set 100' cmt plug (8 5/8" csg shoe @ 4300') w/ 35sx Cl H cmt, WOC. RIH, tag cmt @ 4269', spot 10sx Cl H cmt to bring plug to 4250'. POOH to 1950', set 100' cmt plug across Anyhdrite 1950-1850' w/ 35sx Cl H cmt. POOH to 50', set cmt plug to surface w/ 15sx Cl H cmt. Cut WH, install surface marker, RDPU. Well P&A'd 7/13/91.