

STATE OF NEW MEXICO  
ENERGY AND MINERALS DEPARTMENT

OIL CONSERVATION DIVISION

P. O. BOX 2088  
SANTA FE, NEW MEXICO 87501

Form C-103  
Revised 10-1-77

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

5a. Indicate Type of Lease  
State ☒ Fee ☐

5. State Oil & Gas Lease No.  
E-2466

SUNDRY NOTICES AND REPORTS ON WELLS

DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR.  
USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.

1. OIL <input checked="" type="checkbox"/> WELL GAS <input type="checkbox"/> WELL OTHER- 2. Name of Operator Texaco Inc. 3. Address of Operator PO Box 728, Hobbs, New Mexico 88240 4. Location of Well UNIT LETTER <u>L</u> <u>1980</u> FEET FROM THE <u>South</u> LINE AND <u>330</u> FEET FROM THE <u>West</u> LINE, SECTION <u>2</u> TOWNSHIP <u>14S</u> RANGE <u>33E</u> NMPM. 15. Elevation (Show whether DF, RT, GR, etc.) 4200' GR 12. County Lea	7. Unit Agreement Name 8. Farm or Lease Name Amerada State 9. Well No. 1 10. Field and Pool, or Wildcat Saunders Permo Upper Penn
---	--

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:

SUBSEQUENT REPORT OF:

PERFORM REMEDIAL WORK ☐  
TEMPORARILY ABANDON ☐  
PULL OR ALTER CASING ☐  
OTHER ☐

PLUG AND ABANDON ☐  
CHANGE PLANS ☐  
OTHER ☐

REMEDIAL WORK ☒  
COMMENCE DRILLING OPNS. ☐  
CASING TEST AND CEMENT JOBS ☐  
OTHER ☐

ALTERING CASING ☐  
PLUG AND ABANDONMENT ☐  
OTHER ☐

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

Acidize Permo Penn perms 9766'-9902'

- 1) MIRU pulling unit. Install BOP. Pull tubing and submersible pump.
- 2) RIH with 5 1/2" tubing. Spot 200 gallons acid from 9702'-9902'. Set packer at 9650'. Load backside with 2% KCL water. Pressure up on backside to 500 psi.
- 3) Acidize perms 9766'-9902' with 1500 gallons of 15% NEFE acid, 1 drum Unichem's TH756, 1 drum TH425, and 60 ball sealers. 4 BPM on vacuum.
- 4) Release packer. POH. Run new submersible pump. Place well on production.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

397-3571

SIGNED Ja Head TITLE Hobbs Area Superintendent

DATE 2/19/88

APPROVED BY Orig. Signed by Paul Kautz  
Geologist

TITLE \_\_\_\_\_

DATE \_\_\_\_\_

CONDITIONS OF APPROVAL, IF ANY

FEB 26 1988

RECEIVED

FEB 25 1993  
OED  
HOBBS OFFICE