

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

NEW MEXICO OIL CONSERVATION COMMISSION

Form C-103
Supersedes Old
C-102 and C-103
Effective 1-1-85

5a. Indicate Type of Lease	
State <input checked="" type="checkbox"/>	Fee <input type="checkbox"/>
5. State Oil & Gas Lease No.	
LG-8279	

SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)		
1. <input type="checkbox"/> OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER-		7. Unit Agreement Name
2. Name of Operator John L. Cox		8. Farm or Lease Name State "26"
3. Address of Operator P. O. Box 2217, Midland, Texas 79702		9. Well No. 1
4. Location of Well UNIT LETTER <u>N</u> <u>990</u> FEET FROM THE <u>South</u> LINE AND <u>2310</u> FEET FROM THE <u>West</u> LINE, SECTION <u>26</u> TOWNSHIP <u>12-S</u> RANGE <u>36-E</u> NMPM.		10. Field and Pool, or Wildcat Tatum Morrow (Gas)
15. Elevation (Show whether DF, RT, GR, etc.) 3961' GR		12. County Lea

16. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data NOTICE OF INTENTION TO:		SUBSEQUENT REPORT OF:	
PERFORM REMEDIAL WORK <input type="checkbox"/> TEMPORARILY ABANDON <input type="checkbox"/> PULL OR ALTER CASING <input type="checkbox"/> OTHER <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/> CHANGE PLANS <input type="checkbox"/> OTHER <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/> COMMENCE DRILLING OPNS. <input type="checkbox"/> CASING TEST AND CEMENT JOB <input type="checkbox"/> OTHER <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/> PLUG AND ABANDONMENT <input checked="" type="checkbox"/> OTHER <input type="checkbox"/>

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

- Set CIBP @12,650' with 20' cement on top of plug.
- Set 20 sx cement plug @7050'.
- Set 50 sx cement plug @6060' - Top of plug tagged @5885' - (Recovered 5997' of 5-1/2" casing)
- Set 50 sx cement plug @4995' - Tagged top of plug @4880'.
- Set 50 sx cement plug @2372-2272'.
- Set 50 sx cement plug @575-475'.
- Set 10 sx cement plug @ surface.
- Welded Steel Marker.
- P & A Completed 6-25-88.
- Casing left in hole: 13-3/8" - 525'
8-5/8" - 4945'.
5-1/2" - 8107'.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED <u>Mark Spitzer</u>	TITLE <u>Prodn. Acctg. Mgr.</u>	DATE <u>8/8/88</u>
APPROVED BY <u>[Signature]</u>		DATE <u>8/8/88</u>
CONDITIONS OF APPROVAL, IF ANY:		

OIL & GAS INSPECTOR