

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

NEW MEXICO OIL CONSERVATION COMMISSION

Form C-103
Supersedes Old
C-102 and C-103
Effective 1-1-65

5a. Indicate Type of Lease	
State <input checked="" type="checkbox"/>	Fee <input type="checkbox"/>
5. State Oil & Gas Lease No.	
LG 8279	

SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL <input type="checkbox"/> GAS WELL <input checked="" type="checkbox"/> OTHER <input type="checkbox"/>	7. Unit Agreement Name
2. Name of Operator JOHN L. COX	8. Farm or Lease Name State "26"
3. Address of Operator Box 2217, Midland, Tx 79702	9. Well No. 1
4. Location of Well UNIT LETTER <u>N</u> <u>990</u> FEET FROM THE <u>South</u> LINE AND <u>2310</u> FEET FROM <u>West</u> <u>26</u> <u>12S</u> <u>36E</u> TOWNSHIP <u>26</u> RANGE <u>36E</u> N.M.P.M.	10. Field and Pool, or Wildcat Tatum Morrow (Gas)
15. Elevation (Show whether DF, RT, GR, etc.) 3961 Gr.	12. County Lea

16. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data	
NOTICE OF INTENTION TO:	SUBSEQUENT REPORT OF:
PERFORM REMEDIAL WORK <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	COMMENCE DRILLING CPNS. <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	CASING TEST AND CEMENT JOBS <input type="checkbox"/>
OTHER <input type="checkbox"/>	OTHER <input type="checkbox"/>
PLUG AND ABANDON <input checked="" type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
CHANGE PLANS <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

Reason to P&A: Well uneconomical

- Propose to set CIBP at 12,650' with 20' cement on top.
- Propose to set 50 sx. cement plug at 7000' (Est. recovery 7000' 5½" casing)
- Propose to set 50 sack cement plug at 4895'-4995'.
- Propose to set 50 sack cement plug at 2222'-2372'.
- Propose to set 50 sack cement plug at 475'-575'.
- Propose to set 10 sack cement plug at 0'-10'
- Propose to weld steel marker.

Top of cement per survey 7000' (5½" casing)

THIS DOCUMENT IS NOT TO BE USED AS
EVIDENCE FOR A COURT ACTION OR
FOR ANY OTHER PURPOSE WITHOUT THE
WRITTEN CONSENT OF THE COMMISSION

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED Monte Whitton TITLE Prodn. Acctng. Mgr. DATE 6-15-88

ORIGINAL SIGNED BY FIELD DIVISION
APPROVED BY DISTRICT SUPERVISOR TITLE _____ DATE _____
CONDITIONS OF APPROVAL, IF ANY: