

Submit 3 Copies
to Appropriate
District Office

State of New Mexico
Energy, Minerals and Natural Resources Department

Form C-103
Revised 1-1-89

DISTRICT I
P.O. Box 1980, Hobbs, NM 88240

DISTRICT II
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III
1000 Rio Brazos Rd., Aztec, NM 87410

OIL CONSERVATION DIVISION

P.O. Box 2088
Santa Fe, New Mexico 87504-2088

WELL API NO. 30-025-29664
5. Indicate Type of Lease STATE <input type="checkbox"/> FEE <input checked="" type="checkbox"/>
6. State Oil & Gas Lease No. 21670
7. Lease Name or Unit Agreement Name Speight
8. Well No. 1
9. Pool name or Wildcat Bronco Suluro/Dev.
10. Elevation (Show whether DF, RKB, RT, GR, etc.) NA

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT"
(FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well: OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER
2. Name of Operator Kelly H. Baxter
3. Address of Operator P. O. Box 11193, Midland, TX 79702
4. Well Location Unit Letter A : 660 Feet From The North Line and 660 Feet From The East Line Section 15 Township 13-S Range 38E NMPM Lea County
10. Elevation (Show whether DF, RKB, RT, GR, etc.) NA

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☐
TEMPORARILY ABANDON ☐ CHANGE PLANS ☐
PULL OR ALTER CASING ☐
OTHER: ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐ ALTERING CASING ☐
COMMENCE DRILLING OPNS. ☐ PLUG AND ABANDONMENT ☐
CASING TEST AND CEMENT JOB ☐
OTHER: Run submersible pump ☒

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

Subsequent Report of submitted proposal of 6-28-91

See attached

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Kelly H. Baxter TITLE Owner DATE 9-3-91
TYPE OR PRINT NAME Kelly H. Baxter TELEPHONE NO. 915-682-6191

(This space for State Use)

ORIGINAL SIGNED BY JERRY SEXTON
DISTRICT SUPERVISOR

APPROVED BY _____ TITLE _____ DATE SEP 12 1991
CONDITIONS OF APPROVAL, IF ANY:

SEP 11 1991

000

MOBBS OFFICE

KELLY H. BAXTER

P.O. BOX 11193
MIDLAND, TEXAS 79702

OFFICE TELEPHONE

915/682-6191

FAX NO.:

915/682-9019

Speight #1 Well
Lea County, New Mexico
Subsequent Report

- 6/24/91 - Moved in rigged up. Prepare to run bit and scrapper. Clean out well and run submersible pump. Pull out of hole with tubing and pump. Shut down for night.
- 6/25/91 - Ran in hole with tubing and submersible pump. Made electrical connections. Shut down for night.
- 6/26/91 - Connected electricity. Start submersible pump. Pump locked up and twisted shaft. Shut down for night.
- 6/27/91 - Pull out of hole with tubing and submersible pump. Ran in hole with bit and scraper, got stuck at approximately 8010'. Could not go up or down. Shut down for night.
- 6/28/91 -
- 7/08/91 - Worked to bring up bit and scraper. Had tubing part. Fished tubing, caught on 7/7/91. Brought out of hole. Prepare to acidize. Shut down for night.
- 7/09/91 -
- 7/10/91 - Circulating acid, swabbing, swabbed back. Prepare to and run submersible pump and cable. Pumping ok. Release pulling unit.
- 7/11/91 - Well pumped off. Wait on pulling unit.
- 7/12/91 -
- 7/27/91 - Moved in. Rigged up pulling unit. Pull out of hole with submersible pump. Ran in hole with tubing and packer to acidize and circulate hole. Working on clean out when suffered tubing part. Fished, caught fish. Finish clean out job. Ran submersible pump, would not run. Shut down for night.
- 7/28/91 - Pull out of hole with submersible pump. Ran back in hole with submersible pump and tubing. Set @ 7400'. Start pumping, pumping good. Rigged down pulling unit and put well on production. Job completed.

REC'D

SEP 11 1991

MOBES OFFICE