STATE OF NEW MEXICO ENERGY AND MINERALS DEPARTMENT

MO. OF COPIES RECEIVED	1	
DISTRIBUTION		T
SANTA FE	1	
FILE		1
U.S.G.S.	1	
LAND OFFICE	1	1
OPERATOR	1	

OIL CONSERVATION DIVISION

DISTRIBUTION		P. O. Be	OX 2088			Form C+103 -	
SANTA FE	S.F	NTA FE, NE	W MEXICO 87501		Revised 10-1-1		
FILE		,					
U.S.G.S.					5a. Indicate Typ	e of Lease	
LAND OFFICE					State X	Fee	
OPERATOR					5. State Oil & G	as Lease No.	
					G-9560		
St	INDRY NOTICES AN	D PEPOPTS OF	JWELLC		minin	mmm	
T JANGE ELHT JEU YOM OO)	OF PROPOSALS TO ORICE OF	LE DEELEH ON BEAC	Y WELLS BACK TO A DIFFERENT RESE ICH PROPOSALS.)	RV01=	(//////////////////////////////////////		
1.		TOHA C. 101) FOR 51	ICH PROPOSALS.)		71111111	77/////////////////////////////////////	
OIL X SAB	Ι.				7. Unit Agreemen	nt Name	
2. Name of Operator	J OTHER-				1		
					8. Farm or Lease Name		
	Texaco Inc.				NM "BG" State NCT-1		
3. Address of Operator					9. Well No.		
P. O. Box 728, Hobb	P. O. Box 728, Hobbs, New Mexico 88240				9		
4. Location of Well							
				•	10. Field and Pool, or Wildcat		
UNIT LETTER	UNIT LETTER C . 660 FEET FROM THE NOTTH LINE AND 2310 FEET FROM		FFFT 55	Saunders Permo Upper Penn			
					millin	$mm\ddot{m}$	
THE West LINE	SECTION 14	14	S MANGE 33E				
		TOWNSHIP	MANGE 33E	NMPM.			
	TILL IS Flew	Ttton (Show what a	DF, RT, GR, etc.)	·		7777777777	
					12. County		
46.		94' GR 4213			Lea		
Che	ck Appropriate Box	To Indicate 1	Nature of Notice, Re	0.1			
NOTICE O	F INTENTION TO:	- 10 indicate 1	valure of Notice, Re	eport or Uth	er Data		
• •			SU	IBSEQUENT	REPORT OF:		
PERFORM REMEDIAL WORK							
77	PLU.	G AND ABANDON	REMEDIAL WORK	X	ALTER	ING CASING	
TEMPORARILY ABANDON			COMMENCE DRILLING OPNS	,		<u></u>	
PULL OR ALTER CASING	CHA:	IGE PLANS	CASING TEST AND CEMENT		PEUG X	NO ABANDONMENT	
			OTHER			F	
OTHER					·····		
17. Describe Proposed or Complete work) SEE RULE 1103.	ed Operations (Clearly sta	te all pertinent deti	ils, and sive pertinent do	ing includios a			
work) SEE HOLE 1103.			good perturent da	es, inciditing e	stimatea date of s	tarting any proposed	
1 VIDI DI							
1. MIRU PU.							
Pull rods and			•		•		
3. TIH w/5 1/2" _]	pkr. on 2 7/8" t	ba. Set pki	- @ 9690!				
4. Acidize perform	rations 9764'-90	38' \\\/3000 \	gals. of 15% NEFE				
TH-756 scale	inhihitor and 1	20 hall1	dis. Of 13% NEFE	acid, 16	b gals. of		
5. POH w/tbg. and	a ner	20 Dail Seal	ers @ 3 BPM @ 40) PSI, ISI	P vacuum.		
o. Run ebg., pum	, and rods. Pl	ace well bac	k on production.				
				ů.			
			•				
•							
		•					
				*.		•	
		•					
A. I hereby costify that the 1-7							
8. I hereby certify that the informat	ion above is true and com	plete to the best of	my knowledge and belief.				
1041				. 3	97-3571		
IGNED_ YURON							
		_ TITLE HO	bbs Area Superin	<u>tendent</u>	DATE April	23, 1987	

ORIGINAL SIGNED BY JERRY SEXTON DISTRICT I SUPERVISOR

APR 20 144, ORIA

াশ, এগকালু কেককাল, জাগান, তা প্রভান ক্র কালকালেকী তেনুগোল ক্রিভিন্ন ক্র