

STATE OF NEW MEXICO  
ENERGY AND MINERALS DEPARTMENT

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.B.	
LAND OFFICE	
OPERATOR	

OIL CONSERVATION DIVISION

P. O. BOX 2088

SANTA FE, NEW MEXICO 87501

To: Drawer DD, Artesia, NM 88210

O. C. D.  
ARTESIA OFFICE

RECEIVED

SEP 14 '87

O. C. D.  
ARTESIA OFFICE

Form C-103  
Revised 10-1-78

5a. Indicate Type of Lease	
State <input checked="" type="checkbox"/>	Fee <input type="checkbox"/>
5. State Oil & Gas Lease No.	
V-1881	

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

1. <input checked="" type="checkbox"/> OIL WELL <input type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER-	7. Unit Agreement Name
2. Name of Operator J. Cleo Thompson	8. Farm or Lease Name State 36
3. Address of Operator 4500 First Republic Tower II, Dallas, Texas 75201	9. Well No. 1
4. Location of Well UNIT LETTER I 1980 FEET FROM THE South LINE AND 660' FEET FROM THE East LINE, SECTION 36 TOWNSHIP 13S RANGE 32E NMPM.	10. Field and Pool, or Wildcat Baum zipper Penn
15. Elevation (Show whether DF, RT, GR, etc.) 4292 GR	12. County Lea

16. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:

SUBSEQUENT REPORT OF:

PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input checked="" type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>	CASING TEST AND CEMENT JOB <input type="checkbox"/>	

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

To plug well in accordance with New Mexico regulations. Well Not Commercial.

Detail Plugging procedure is: Set cast iron bridge plug above perforations and cap with 35 feet of cement; Then load hole with 10lb salt gel; Set 100' cement plug across Glorietta Zone; Set 100' cement plug across San Andres Zone; Will bring cement into shoes if intermediate string not circulated; Will set a stubb plug in and out of plug and tag it; Will set 100' plug at casing shoes and if exposed will be tagged; Set 10 sacks cement for surface plug and marker.

100' PLUG AT 400'

THIS WORK SHALL BE NOTICED 24 HOURS PRIOR TO THE BEGINNING OF PLUGGING OPERATIONS FOR THE C-103 TO BE APPROVED.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED Jerry M. Sexton TITLE Agent DATE September 11, 1987

ORIGINAL SIGNED BY JERRY SEXTON  
DISTRICT I SUPERVISOR

APPROVED BY \_\_\_\_\_ TITLE \_\_\_\_\_ DATE OCT 26 1987

CONDITIONS OF APPROVAL, IF ANY:

RECEIVED  
OCD  
SEP 21 1987  
HOBBS OFFICE

RECEIVED  
OCD  
OCT 2 8 1987  
HOBBS OFFICE