DISTRIBUTION	OIL CONSERVATION DIVISION P. O. BOX 2088 SANTA FE, NEW MEXICO 87501		Form C-103 Revised 10-1-78	
U.S.O.S. LAND OFFICE OPERATOR			State State Oil & Gas Lease No.	
(DO NOT USE THIS FORM FOR PROP	NOTICES AND REPOR	OR PLUG BACK TO A DIPPERENT RESERVOIR.		
. 811	OTHER-		7, Unit Agreement Name	
Newhall Resources			8. Form or Lease Hame Speight	
P. O. Box 8629, Mid	and, Texas 79708		9. Well No. 2	
. Location of Well UNIT LETTER H	330 FEET FROM THE	ast 1650	Bronco/SiluroDevonian	
North LINE, SECTION	15			
	15. Elevation (Show	whether DF, RT, GR, etc.) 3804.6	12. County Lea	
PERFORM BEMEDIAL WORR TEMPORARILY ABANDON PULL OR ALTER CABINS	PLUE AND ABAN Change Plans	REMEDIAL WORK COMMENCE DRILLING OPHS. CASING TEST AND CEMENT JQS OTHER	ALTERING CASING PLUG AND ABANDONMENT	
For plug and abando at 9300' and squeez a 100 sack cement p	ning the Speight We e cement the Wolfc lug from 4400' to	ell No. 2 Newhall proposes to amp perforations with 100 sac 4200' and a 100 sack cement p steel plate welded on the 1	o set a cement retainer cks of neat cement, set plug from 500' to 250'	
100 ph	z ut 70-0	THE COMMISSION MUST BE IN HOURS PRIOR TO THE BEGIND COMMANDES FOR TO BE APPROVED.		

Production Manager

8. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

ORIGINAL SIGNED BY JERRY SEXTON DISTRICT I SUPERVISOR