

STATE OF NEW MEXICO  
ENERGY AND MINERALS DEPARTMENT

OIL CONSERVATION DIVISION  
P. O. BOX 2088  
SANTA FE, NEW MEXICO 87501

Form C-103  
Revised 10-1-78

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

5a. Indicate Type of Lease	
State <input checked="" type="checkbox"/>	Fee <input type="checkbox"/>
5. State Oil & Gas Lease No.	

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR.  
USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL <input type="checkbox"/> GAS <input type="checkbox"/> OTHER- <input type="checkbox"/>		7. Unit Agreement Name	
2. Name of Operator TXO Production Corp.		8. Farm or Lease Name Yates State	
3. Address of Operator 900 Wilco Bldg., Midland, TX 79701		9. Well No. 1	
4. Location of Well UNIT LETTER P 660 FEET FROM THE South LINE AND 850 FEET FROM THE East LINE, SECTION 16 TOWNSHIP 12-S RANGE 38-E NMPM.		10. Field and Pool, or Wildcat Gladiola Wolfcamp	
15. Elevation (Show whether DF, RT, GR, etc.) 3821 GL & 3833 KB		12. County Lea	

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data  
NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>

SUBSEQUENT REPORT OF:

REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
CASING TEST AND CEMENT JOBS <input type="checkbox"/>	OTHER <input checked="" type="checkbox"/> Treating

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

10-13-87 Ran temp svy. Top of cmt @ 8670'.  
10-14-87 TIH w/bit, DCs & 295 jts 2 3/8" 4.7# N-80 tbg.  
10-16-87 Perf Wolfcamp 9506-16' w/2 SPF w/3 1/8" csg gamma gun, 22 holes. Spot 250 gals 15% NEFE w/add @ 9514'. ISDP 3600#, 3 min vac.  
10-17-87 Acid w/2500 gals 15% NEFE w/14 ball sealers. ISDP 2800#, 5 min 400#, 8 min vac.  
10-18-87 Swabbing.  
thru  
10-21-87  
10-22-87 Acid w/5000 gals 15% crosslink & CO2. Flush w/2% KCL & CO2. ISDP 4700#, 5 min 3000#, 10 min 2100#, 15 min 1500#. Swabbing.  
10-23-87 Swab testing.  
thru  
10-25-87

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED Beth Cune

TITLE Secretary

DATE 11-6-87

Orig. Signed by  
Paul Kautz  
Geologist

APPROVED BY \_\_\_\_\_

TITLE \_\_\_\_\_

DATE \_\_\_\_\_

NOV 12 1987

CONDITIONS OF APPROVAL, IF ANY:

RECEIVED

NOV 10 1987

OCD  
HIGGS OFFICE