

Submit to Appropriate
District Office
State Lease - 6 copies
Fee Lease - 5 copies

State of New Mexico
Energy, Minerals and Natural Resources Department

Form C-101
Revised 1-1-89

OIL CONSERVATION DIVISION

DISTRICT I
P.O. Box 1980, Hobbs, NM 88240

P.O. Box 2088
Santa Fe, New Mexico 87504-2088

DISTRICT II
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III
1000 Rio Brazos Rd., Aztec, NM 87410

API NO. (assigned by OCD on New Wells)

30-025-30149

5. Indicate Type of Lease

STATE ☒

FEE ☐

6. State Oil & Gas Lease No.

LG 4903

APPLICATION FOR PERMIT TO DRILL, DEEPEN, OR PLUG BACK

1a. Type of Work:

DRILL ☐

RE-ENTER ☐

DEEPEN ☐

PLUG BACK ☒

b. Type of Well:

OIL
WELL ☐

GAS
WELL ☐

OTHER

RECOMPLETE

SINGLE
ZONE ☐

MULTIPLE
ZONE ☐

7. Lease Name or Unit Agreement Name

Lazy Tree State Unit

2. Name of Operator

YATES PETROLEUM CORPORATION

8. Well No.

1

3. Address of Operator

105 South 4th St., Artesia, NM 88210

9. Pool name or Wildcat

Undesignated

4. Well Location

Unit Letter A : 660 Feet From The North Line and 660 Feet From The East Line

Section 12 Township 13S Range 32E NMPM Lea County

10. Proposed Depth
12100'

11. Formation
Atoka-Morrow

12. Recovery or C.T.
Pulling Unit

13. Elevations (Show whether DF, RT, GR, etc.)

4305.7' GR

14. Kind & Status Plug. Bond

Blanket

15. Drilling Contractor

-

16. Approx. Date Work will start

When approved.

17. PROPOSED CASING AND CEMENT PROGRAM

SIZE OF HOLE	SIZE OF CASING	WEIGHT PER FOOT	SETTING DEPTH	SACKS OF CEMENT	EST. TOP
17 1/2"	13-3/8"	54.5#	472'	475 sx (in place)	
11"	8-5/8"	32#	4210'	1850 sx (in place)	
7-7/8"	5 1/2"	20 & 17#	12100'	400 sx (in place)	

Propose to swab existing perforations 11478-483'. Set standing valve in packer 11436' and pull tubing. Perforate 11138-11240' w/14 holes. GIH with tubing, packer and RBP. Acidize perforations 11138-11240' with 2000 gals 20% NEFE acid and ball sealers. Test well.

Move RBP to 10800' and pressure test. Spot acid and set packer at 10630' and pressure test. Perforate Strawn through tubing 10684-690' w/12 holes (2 SPF). Break down perforations and swab test. If necessary, acidize with 2000 gals 20% NEFE acid. Test well.

IN ABOVE SPACE DESCRIBE PROPOSED PROGRAM: IF PROPOSAL IS TO DEEPEN OR PLUG BACK, GIVE DATA ON PRESENT PRODUCTIVE ZONE AND PROPOSED NEW PRODUCTIVE ZONE. GIVE BLOWOUT PREVENTER PROGRAM, IF ANY.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE

Juanita Goodlett

TITLE Production Supervisor

DATE 3-30-89

TYPE OR PRINT NAME

Juanita Goodlett

TELEPHONE NO. 505/748-147

(This space for State Use)

ORIGINAL SIGNED BY JERRY SEXTON
DISTRICT I SUPERVISOR

APPROVED BY

TITLE

DATE

CONDITIONS OF APPROVAL, IF ANY:

APR 3 1989