

Explanation for the following section of the NM Oil Conservation Division Manual for Back-Pressure Tests.

II.

A.

2.C) The Ranger No. 17 well pressure was not drawn-down at least 25% during the test due to a concern that water coning may occur.