

DISTRICT I
P.O. Box 1980, Hobbs, NM 88240

DISTRICT II
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III
1000 Rio Brazos Rd., Aztec, NM 87410

OIL CONSERVATION DIVISION
P.O. Box 2088
Santa Fe, New Mexico 87504-2088

WELL API NO. 30-025-33160
5. Indicate Type of Lease STATE <input type="checkbox"/> FEE <input checked="" type="checkbox"/>
6. State Oil & Gas Lease No.
7. Lease Name or Unit Agreement Name GECKO Lowe et al
8. Well No. 1-Y
9. Pool name or Wildcat Wildcat
10. Elevation (Show whether DF, RKB, RT, GR, etc.) 3,854' CL

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT"
(FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well: OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER
2. Name of Operator GECKO
3. Address of Operator 310 W. Wall, Suite 702; LB-106, Midland, TX 79701
4. Well Location Unit Letter C : 984 Feet From The North Line and 2306 Feet From The West Line Section 35 Township 13S Range 37E NMPM Lea Country

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data	
NOTICE OF INTENTION TO:	SUBSEQUENT REPORT OF:
PERFORM REMEDIAL WORK <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>
OTHER: <input type="checkbox"/>	PLUG AND ABANDONMENT <input checked="" type="checkbox"/>
	CASING TEST AND CEMENT JOB <input type="checkbox"/>
	OTHER: <input type="checkbox"/>

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

Approved as to plugging of the Well Bore.
Liability under bond is retained until
surface restoration is completed.

- 2-27-97 - MIRU. Cut csg @ 1525'.
3-03-97 - Jack w/ OCD on location. Csg not free; pulled on csg. Csg parted. Speared fish & POOH W/ 60' csg.
Cut csg @ 1267'.
3-04-97 - Jack w/ OCD on location. Speared into csg; not free. Circulated hole & pumped 100 sx C cmt @ 1575'. WOC.
3-05-97 - Jack w/ OCD on location. RIH w/ tbg & tagged plug @ 1188'. Cut csg @ 876'. POOH w/ csg.
Circulated hole w/ mud & pumped 60 sx C cmt @ 941'. WOC & tagged plug @ 769'. Circulated hole w/ mud & pumped 70 sx C cmt @ 564'. WOC.
3-06-97 - RIH w/ tbg & tagged plug @ 435'. POOH w/ tbg to 30' & pumped 25 sx C cmt to surface. POOH.
RD. Cut off wellhead & capped well. Installed dry hole marker. Leveled cellar, cleaned location.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Steve L. Thomson TITLE pPresident DATE 03/18/97
TYPE OR PRINT NAME Steve L. Thomson TELEPHONE NO. 915-686-0121

(This space for State Use)

APPROVED BY GARY W. WINK TITLE QC FIELD REPRESENTATIVE II/STAFF MANAGER DATE JAN 28 1997
CONDITIONS OF APPROVAL, IF ANY: