

OIL CONSERVATION DIVISION
P.O. Box 2088
Santa Fe, New Mexico 87504-2088

DISTRICT I
P.O. Box 1980, Hobbs, NM 88240

DISTRICT II
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III
1000 Rio Brazos Rd., Aztec, NM 87410

WELL API NO. 30-025-33200
5. Indicate Type of Lease STATE <input type="checkbox"/> FEE <input checked="" type="checkbox"/>
6. State Oil & Gas Lease No.
7. Lease Name or Unit Agreement Name LOWE 20
8. Well No. 2
9. Pool name or Wildcat BRONCO; WOLFCAMP, SOUTHWEST

10. Elevation (Show whether DF, RKB, RT, GR, etc.) 3830'
--

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well: OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/>
2. Name of Operator MARALO, INC.
3. Address of Operator P. O. BOX 832, MIDLAND, TX 79702
4. Well Location Unit Letter G : 1650 Feet From The NORTH Line and 1980 Feet From The EAST Line Section 20 Township 13S Range 38E NMPM LEA County

10. Elevation (Show whether DF, RKB, RT, GR, etc.) 3830'
--

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data	
NOTICE OF INTENTION TO:	SUBSEQUENT REPORT OF:
PERFORM REMEDIAL WORK <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>
OTHER: <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
	CASING TEST AND CEMENT JOB <input type="checkbox"/>
	ACIDIZE EXISTING PERFS & <input type="checkbox"/>
	OTHER: OPEN ADDITIONAL WOLFCAMP PAY <input checked="" type="checkbox"/>

07/27/00 UNSET RBP COVERING EXISTING PERFS @ 9560-69, 9607-15. TESTED IN HOLE TO 8000 PSI ABOVE SLIPS, SET PKR @ 9510; PREP TO ACIDIZE PERFS. 9560 - 9615'.

07/28-31/00 SPOTTED 200 GALS 15% NEFE ACID & SET PKR @ 9510'. SPOTTED 1800 GALS 15% NEFE ACID FROM BTM OF TBG. PRESSURE REMAINED SAME THROUGHOUT JOB. RU TO SWAB. RBP @ 9368' WL DEPTH, TESTED TO 1000 PSI & HELD. BTM OF TBG @ 9338'.

08/01/00 SPOTTED 200 GALS 15% NEFE ACID FROM 9338' UP. SHOT 4 SPF @ 9298 - 9310', 9317 - 9322', 9330 - 9338', 112 HOLES IN ALL. CONTINUED TREATING PERFS W/2000 GALS 15% NEFE ACID. MAX PRESSURE 4200 PSI, MIN PRESSURE 3730 PSI.

08/02-04/00 SWABBED, NO BOP. SET TBG ANCHOR W/18 POINTS TENSION. NU TBG BONNET. TAC @ 9300'. SN @ 9425'. BTM OF BULLPLUG MUD ANCHOR JT @ 9462'. RIH W/2-1/2" x 1-1/2" x 35' PUMP W/8' GAS ANCHOR AND NORRIS TYPE 90 RODS. LOADED AND TESTED PUMP & TBG TO 500 PSI, BOTH OK. PUT WELL PUMPING TO BATTERY FROM PERFS 9298-9338', 9380-9434', 9560-9615'. *J*

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE *Dorothea Logan* TITLE **REGULATORY ANALYST** DATE **AUGUST 21, 2000**
TYPE OR PRINT NAME **DOROTHEA LOGAN** TELEPHONE NO. **915 684-7441**

(This space for State Use)

APPROVED BY _____ TITLE _____ DATE _____
CONDITIONS OF APPROVAL, IF ANY: