

Submit 3 Copies  
to Appropriate  
District Office

State of New Mexico  
Energy Minerals and Natural Resources Department

Form C-103  
Revised 1-1-89

DISTRICT I  
P.O. Box 1980, Hobbs, NM 88240

DISTRICT II  
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III  
1000 Rio Brazos Rd., Aztec, NM 87410

OIL CONSERVATION DIVISION  
P.O. Box 2088  
Santa Fe, New Mexico 87504-2088

WELL API NO. 30-025-33275
5. Indicate Type of Lease STATE <input checked="" type="checkbox"/> FEE <input type="checkbox"/>
6. State Oil & Gas Lease No. VA-0357
7. Lease Name or Unit Agreement Name Papalotes Unit
8. Well No. 1
9. Pool name or Wildcat Wildcat Morrow

SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEFEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)	
1. Type of Well: OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/>	
2. Name of Operator YATES PETROLEUM CORPORATION	
3. Address of Operator 105 South 4th St., Artesia, NM 88210	
4. Well Location Unit Letter <u>I</u> : <u>1960</u> Feet From The <u>South</u> Line and <u>330</u> Feet From The <u>East</u> Line Section <u>34</u> Township <u>14S</u> Range <u>34E</u> NMPM <u>Lea</u> County <u></u>	
10. Elevation (Show whether DF, RKB, RT, GR, etc.) 4092' GR	

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data	
NOTICE OF INTENTION TO:	SUBSEQUENT REPORT OF:
PERFORM REMEDIAL WORK <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>
OTHER: <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
	CASING TEST AND CEMENT JOB <input type="checkbox"/>
	OTHER: <u>Drill DV tool</u> <input checked="" type="checkbox"/>

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

4-16-96 - Cleaned location and set anchors. Moved in and rigged up pulling unit.

4-17-96 - TIH with bit, stabilizer, drill collars and tubing. Drilled out DV tool at 10030'. Tested to 1000 psi. TIH and tagged cement at 13520'. Drilled out at 13613'. Displaced hole with 2% KCL. Pulled 30 stands. Shut in.

4-18-96 - TOOH with tubing and laid down drill collars. TIH with bit and scraper to 13612'. TOOH. Rigged up wireline. TIH with logging tools and ran GR/CBL/CCL log. Shut well in.

4-19-96 - Shut in.

4-20-22-96 - TIH with tubing.

4-23-96 - TIH with 2-7/8" tubing open ended to 13572'. Nippled down BOP. Nippled up tree. Shut well in. Waiting on orders.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Rusty Klein TITLE Production Clerk DATE 4-25-96

TYPE OR PRINT NAME Rusty Klein TELEPHONE NO. 505/748-1471

(This space for State Use)

ORIGINAL SIGNED BY JERRY FENTON

APR 30 1996

APPROVED BY

TITLE

DATE

CONDITIONS OF APPROVAL, IF ANY:

20272820  
↑  
APR 1985  
Received  
Hobbs  
OCD