

District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 South First, Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
2040 South Pacheco, Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources

Oil Conservation Division
2040 South Pacheco
Santa Fe, NM 87505

Form C-101
Revised March 17, 1999

Submit to appropriate District Office
State Lease - 6 Copies
Fee Lease - 5 Copies

☐ AMENDED REPORT

APPLICATION FOR PERMIT TO DRILL, RE-ENTER, DEEPEN, PLUGBACK, OR ADD A ZONE

Operator Name and Address RICKS EXPLORATION, INC. 210 PARK AVENUE 3000 OKLAHOMA TOWER OKLAHOMA CITY, OKLAHOMA 73102		OGRID Number 168489
		API Number 30-025-34922
Property Code 25306	Property Name BURRUS	Well No. 1

Surface Location

UL or lot no.	Section	Township	Range	Lot 1/4	Feet from the	North/South line	Feet from the	East/West line	County
0	22	12S	38E		900'	South	1859'	East	LEA

Proposed Bottom Hole Location If Different From Surface

UL or lot no.	Section	Township	Range	Lot 1/4	Feet from the	North/South line	Feet from the	East/West line	County
Proposed Pool 1 TRINITY-WOLFCAMP (59890)					Proposed Pool 2				

Work Type Code P	Well Type Code O	Cable/Rotary R	Lease Type Code P	Ground Level Elevation 3798'
Multiple NO	Proposed Depth 9100'	Formation WOLFCAMP	Contractor UNKNOWN	Spud Date WHEN APPROVED

Proposed Casing and Cement Program

Hole Size	Casing Size	Casing weight/foot	Setting Depth	Sacks of Cement	Estimated TCC
17 1/2"	13 3/8"	54.5	400'	375 Sx.	Surface
12 1/2"	9 5/8"	36	4500'	1235 Sx.	Surface
7 7/8"	5 1/2"	20	12,200'	730 Sx.	7000'

Describe the proposed program. If this application is to DEEPEN or PLUG BACK, give the data on the present productive zone and proposed new productive zone. Describe the blowout prevention program, if any. Use additional sheets if necessary.

1. Trip out of hole with tubing. Rig up wireline Company, run in hole with CIBP set plug at 9100'. Dump cement on top of CIBP.
2. Perforate Wolfcamp with a 4" hollow carrier gun at 9057-63, 9042-47, 9020-32 with 4 shots per foot.
3. Go in hole with tubing and packer to 8950'. Set packer and swab test Perfs 9063-9020'. Rig up and acidize perfs with 1000 gal. of 15% HCl and 80 ball sealers, displace with 2% KCl, break down perfs and put acid away.
4. Swab back load and place well on pump.

Permit Expires 1 Year From Approval
Date Unless Drilling Underway
Plugback

I hereby certify that the information given above is true and complete to the best of my knowledge and belief.

Signature:

Printed name:

Title:

Date:

Phone:

OIL CONSERVATION DIVISION

Approved by: ORIGINAL SIGNED BY CARIS WILLIAMS
DISTRICT ENGINEER

Title:

Approval Date:

Expiration Date:

Conditions of Approval:



NAD 27 TXSPC NCZ Y=624727 X=294585		OPERATOR CERTIFICATION <i>I hereby certify that the information contained herein is true and complete to the best of my knowledge and belief.</i> <i>Joe T. Janica</i> <u>Signature</u> Joe T. Janica <u>Printed Name</u> Agent <u>Title</u> 01/02/01 <u>Date</u>									
NAD 27 NMSPC EZ Y=824152 X=882579 1859' 900'		SURVEYOR CERTIFICATION <i>I hereby certify that the well location shown on this plat was plotted from field notes of actual surveys made by me or under my supervision, and that the same is true and correct to the best of my belief.</i> JANUARY 26, 2000 <u>Date Surveyed</u> LWP <u>Signature & Seal of Professional Surveyor</u> <i>Ronald J. Edson</i> 1-27-2000 00-11-0073 <table border="1" style="width: 100%; border-collapse: collapse; margin-top: 10px;"> <tr> <td style="width: 60%;">Certificate No.</td> <td style="width: 20%;">RONALD J. EDSON</td> <td style="width: 20%;">3239</td> </tr> <tr> <td></td> <td>GARY EDSON</td> <td>12541</td> </tr> <tr> <td></td> <td>MACON McDONALD</td> <td>12186</td> </tr> </table>	Certificate No.	RONALD J. EDSON	3239		GARY EDSON	12541		MACON McDONALD	12186
Certificate No.	RONALD J. EDSON	3239									
	GARY EDSON	12541									
	MACON McDONALD	12186									

