Submit 3 Copies To Appropriate District	State of New Mexico			Form C-103	
Office District I	Energy, Minerals and Natural Resources			Revised March 25, 1999	
1625 N. French Dr., Hobbs, NM 88240			WELL API NO.		
District II	OIL CONSERVATION DIVISION			30-025-35374	
811 South First Artesia, NM 88210 District III	1220 South St. Francis Dr.			5. Indicate Type of	of Lease
1000 D: D D1 A-4 NM 07410				X FEE	
District IV Santa Pe, Nivi 67505			6. State Oil & G	as Lease No.	
1220 S. St. Francis Dr., Santa Fe, NM 87505				VA-1913	
SUNDRY NOTICES AND REPORTS ON WELLS				7. Lease Name or	Unit Agreement Name:
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A					
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH				Indigo State U	Init
PROPOSALS.)  1. Tyme of Walls					
1. Type of Well: Oil Well Gas Well X Other					
2. Name of Operator				7. Well No.	
Yates Petroleum Corporation				8. Pool name or Wildcat Four Lake	
3. Address of Operator				, =:	
105 S. 4 <sup>th</sup> Street Artesia, NM 88210				Wilde <del>al</del> Mississippian	
4. Well Lecation					
	//O Cont Comments & Co	udh	line and OOA	fact from the	Nost line
Unit Letter M:	feet from the 30	UIN	_ nne and _ 770	reet from the	ine ine
	t: 100 D		35E NMP	м <b>Lea</b>	County
Section 5 To	wnship 128 Ran 10. Elevation (Show wh				County
	10. Elevation (Snow wi			2.)	
		4150		D 4 041	Data
	ppropriate Box to Ind	icate N	ature of Notice,	Report or Other	Data
NOTICE OF IN	TENTION TO:		SUB	SEQUENT RE	PORT OF:
PERFORM REMEDIAL WORK	PLUG AND ABANDON		REMEDIAL WOR	к П	ALTERING
PERFORM REMEDIAL WORK	FEOG AND ABANDON		TEMEDIAL WOR		CASING
TEMPORAFILY ABANDON	CHANGE PLANS		COMMENCE DR	ILLING OPNS.	PLUG AND ABANDONMENT
	MULTIPLE		CASING TEST A	ND —	ABANDONNEN
PULL OR ALTER CASING	COMPLETION		CEMENT JOB		
OTHER:			OTHER: run and	d cement production	casing
Describe proposed or completed op	perations. (Clearly state al	ll pertine	nt details, and give	pertinent dates, incl	uding estimated date of
starting any proposed work). SEE	RULE 1103. For Multiple	Comple	tions: Attach wellb	ore diagram of prop	oosed completion or
recompilation.	-	-			
8/25/01 - Run DST #1 12,002-1	2.151' Morrow				Contraction of the Contraction o
8/30/01 – Reached TD at 12,966' at 10:15 PM.					
8/31/01 – Ran open hole logs. Logger's TD 12,969'.					
9/2/01 – Ran 314 joints (12,977.06') casing set at 12,966' as follows:					
7/2/01 - Rain 5/4 Johns (12,777.00) casing set at 12,700 as tollows:					
26 joints 4-1/2" P-110 SB (1048.33')					
1 joint 4-1/2" P-110 marker (21.12')					
287 joints 4-1/2" P-110 varn (	11,907.61")			্তি	
Float shoe set at 12,966'. Float	at collar set at 12,924".		O. 43 . FØ FLOF	6.01 to 10.00	325 - 07616"
Cemented with 450 sxs 15:61:	11 Poz H CSE + 3# salt	r + 5# L	CMI + .5% FL25	(yia 1.61, wt 13.2	25 25 25 25 5 5 5 5 5 5 5 5 5 5 5 5 5 5
PD at 5:06 PM. Bumped plug		Held C	OK.		
Rig released at 11:00 PM 9/2/	01.				
I hereby certify that the information	n above is true and comple	ete to the	best of my knowled	age and belief.	
1 - 11					5 - I 00 0000
SIGNATURE Service Cla	TITL	E <u><b>E</b></u>	<u>ngineering Tec</u>	<u>hnician</u> DATE_	February 22, 2002
·	7				>
Type or print name Susan He	rpin		ORIGINAL SIC	NED By Telephone	e No. 505-748-1471
(This space for State use)			PALLE K	∆   <b>†7</b>	
•			PETROLEUM É	VICIVILLO JOTA	MAR 27 2002
APPPROVED BY		_TITLE_	- MILLOFFOM E	INGINEEK	DATE
Conditions of approval, if any:					