Submit 3 Copies To Appropriate District Office	State of)	OMICO		Fo	
District I	Energy, Minera	ls and Nati	ural Resources		Revised Ma	rch 25, 1
1625 N. French Dr., Hobbs, NM 88240				WELL API NO		
District II 1301 W. Grand Ave., Artesia, NM 88210	OIL CONSEI	RVATION	N DIVISION	5 Indian m	30-025-36018	3
District III	1220 Sou	ith St. Fra	ncis Dr.	5. Indicate Type STATE		
1000 Rio Brazos Rd., Aztec, NM 87410 District IV	Santa	Fe, NM 8	7505		FEE Gas Lease No.	<u> </u>
1220 S. St. Francis Dr., Santa Fe, NM		,		J. State Off &	C Gas Least IVO.	
87505 SUNDRY NOTIC	CES AND REPORTS	ONWELL	3	7 Lange Marris	on Timid A	and N
(DO NOT USE THIS FORM FOR PROPOS DIFFERENT RESERVOIR. USE "APPLIC. PROPOSALS.)	ALS TO DRILL OR TO DE	EEPEN OR PL	UG BACK TO A	/. Lease Name	e or Unit Agreem	ent Nam
Type of Well: Oil Well					State "22"	
				8. Well No.	111	- -
3. Address of Operator	ks exploration inc.			9. Pool name o	#1	
110 W. Louisiana	, Ste 410 Midland	d, TX 7970	1		nity; Wolfcamp	
4. Well Location	,	,	·	1111	, ii oneamp	
Unit Letter <u>H</u> :	2310 feet from	m tha N-	anth 1: 3	000 -	. d P	4.
		m the No	orth line and _	990 feet fron	n the <u>East</u>	line
Section 22	Township	12S	Range 38E		County	Lea
	10. Elevation (Show			c.)		
11 Check A	ppropriate Box to I	3799' Indicate N		Denort or Oth	or Dota	
NOTICE OF INT	PPIOPITATE BOX TO I	murait N		SEQUENT R		
PERFORM REMEDIAL WORK	PLUG AND ABANDO	N 🗆	REMEDIAL WOR		ALTERING C	ASING
<u> </u>		_		_		.0.110
TEMPORARILY ABANDON 🔲	CHANGE PLANS		LOCAMENCE DD		D1 110 111-	1
			COMMENCE DR	ILLING OPNS.	PLUG AND	
PULL OR ALTER CASING	MULTIPLE COMPLETION		CASING TEST AI CEMENT JOB	_	PLUG AND ABANDONME	
OTHER:	COMPLETION		CASING TEST AI CEMENT JOB OTHER:	ND Completion	ABANDONME	NT
OTHER:	COMPLETION operations. (Clearly s	□ □ tate all perti	CASING TEST AI CEMENT JOB OTHER: nent details, and gi	Completion	ABANDONME	NT
OTHER: 2. Describe proposed or completed starting any proposed work). SEI recompilation. 1/20/02 – MIRU. PU 4-3/4" bit, 5 ½ 1/21/02 – Ru Baker Atlas & ran CBL Perf 9104'-9110'. RIH w/-	operations. (Clearly s E RULE 1103. For Mu "csg scraper on 2 7/8"	tate all perticultiple Comp 'tbg. Tag F 83'-7700'.	CASING TEST AI CEMENT JOB OTHER: nent details, and girpletions: Attach we	Completion ve pertinent dates, ellbore diagram of	ABANDONME including estimate proposed complete the compl	etion or
OTHER: 2. Describe proposed or completed starting any proposed work). SEI recompilation. 1/20/02 - MIRU. PU 4-3/4" bit, 5 ½ 1/21/02 - Ru Baker Atlas & ran CBL Perf 9104'-9110'. RIH w/1/23/02 - Swab. 1/27/02 - RU Baker Atlas. RIH w/C	operations. (Clearly see RULE 1103. For Multiple Control of the Co	tate all pertialtiple Comp 'tbg. Tag F 83'-7700'.	CASING TEST AI CEMENT JOB OTHER: nent details, and girpletions: Attach were PBTD @ 9184'. PUTOC @ 3470'. Pe	Completion ve pertinent dates, ellbore diagram of JH to 9125'. Pick rf Wolfcamp w/4"	including estimate proposed complete the com	ated date etion or n w/1 Sl
OTHER: 2. Describe proposed or completed starting any proposed work). SEI recompilation. 1/20/02 – MIRU. PU 4-3/4" bit, 5 ½ 1/21/02 – Ru Baker Atlas & ran CBL Perf 9104'-9110'. RIH w/1/23/02 – Swab. 1/27/02 – RU Baker Atlas. RIH w/C & pkr to 8942'. Swab.	operations. (Clearly see RULE 1103. For Musical Section 27/8). GR/CCL log from 91 tbg & pkr to 9040'. To EIBP set @ 9095'. LD	tate all pertialtiple Comp 'tbg. Tag F 83'-7700'. est csg. & test to 20	CASING TEST AI CEMENT JOB OTHER: nent details, and girpletions: Attach we PBTD @ 9184'. PUTOC @ 3470'. Perf Wolfcam	Completion ve pertinent dates, ellbore diagram of JH to 9125'. Pick rf Wolfcamp w/4"	including estimate proposed complete the com	ated date etion or n w/1 Sl
OTHER: 2. Describe proposed or completed starting any proposed work). SEI recompilation. 1/20/02 - MIRU. PU 4-3/4" bit, 5 ½ 1/21/02 - Ru Baker Atlas & ran CBL Perf 9104'-9110'. RIH w/1/23/02 - Swab. 1/27/02 - RU Baker Atlas. RIH w/C & pkr to 8942'. Swab. 2/02/02 - Acidize perfs from 9052'-9	operations. (Clearly see RULE 1103. For Musical Section 27/8). GR/CCL log from 91 tbg & pkr to 9040'. To EIBP set @ 9095'. LD	tate all pertialtiple Comp 'tbg. Tag F 83'-7700'. est csg. & test to 20	CASING TEST AI CEMENT JOB OTHER: nent details, and girpletions: Attach we PBTD @ 9184'. PUTOC @ 3470'. Perf Wolfcam	Completion ve pertinent dates, ellbore diagram of JH to 9125'. Pick rf Wolfcamp w/4"	including estimate proposed complete the com	ated date etion or n w/1 SI
OTHER: 2. Describe proposed or completed starting any proposed work). SEI recompilation. 1/20/02 - MIRU. PU 4-3/4" bit, 5 ½ 1/21/02 - Ru Baker Atlas & ran CBL Perf 9104'-9110'. RIH w/1/23/02 - Swab. 1/27/02 - RU Baker Atlas. RIH w/C & pkr to 8942'. Swab. 2/02/02 - Acidize perfs from 9052'-92/04/02 - Swab.	operations. (Clearly see ERULE 1103. For Musical Section of the Se	tate all pertialtiple Comp 'tbg. Tag F 83'-7700'. est csg. & test to 20	CASING TEST AI CEMENT JOB OTHER: nent details, and girpletions: Attach we PBTD @ 9184'. PUTOC @ 3470'. Pe	Completion ve pertinent dates, ellbore diagram of JH to 9125'. Pick rf Wolfcamp w/4'	including estimate proposed complete the com	ated date etion or n w/1 Sl
OTHER: 2. Describe proposed or completed starting any proposed work). SEI recompilation. 1/20/02 - MIRU. PU 4-3/4" bit, 5 ½ 1/21/02 - Ru Baker Atlas & ran CBL Perf 9104'-9110'. RIH w/1/23/02 - Swab. 1/27/02 - RU Baker Atlas. RIH w/C & pkr to 8942'. Swab. 2/02/02 - Acidize perfs from 9052'-92/04/02 - Swab. 2/10/02 - RU Hydro-Testers. TIH w/C	operations. (Clearly see ERULE 1103. For Muser' csg scraper on 2 7/8' L/GR/CCL log from 91' tbg & pkr to 9040'. To EIBP set @ 9095'. LD 9086' w/3400 gals 90/10' tbg & set @ 9073'. To Eithe Elbert & Set &	tate all pertialtiple Comp 'tbg. Tag F 83'-7700'. est csg. & test to 20	CASING TEST AI CEMENT JOB OTHER: nent details, and girpletions: Attach we PBTD @ 9184'. PUTOC @ 3470'. Pe	Completion ve pertinent dates, ellbore diagram of JH to 9125'. Pick rf Wolfcamp w/4'	including estimate proposed complete the com	ated date etion or n w/1 S
OTHER: 2. Describe proposed or completed starting any proposed work). SEI recompilation. 1/20/02 - MIRU. PU 4-3/4" bit, 5 ½ 1/21/02 - Ru Baker Atlas & ran CBL Perf 9104'-9110'. RIH w/ 1/23/02 - Swab. 1/27/02 - RU Baker Atlas. RIH w/C & pkr to 8942'. Swab. 2/02/02 - Acidize perfs from 9052'-92/04/02 - Swab. 2/10/02 - RU Hydro-Testers. TIH w/ 2/11/02 - Ran rods & pmp. LD & testers.	operations. (Clearly see RULE 1103. For Musical Section of the RULE 11	tate all pertialtiple Comp 'tbg. Tag F 83'-7700'. est csg. & test to 20	CASING TEST AI CEMENT JOB OTHER: nent details, and girpletions: Attach we PBTD @ 9184'. PUTOC @ 3470'. Pe	Completion ve pertinent dates, ellbore diagram of JH to 9125'. Pick rf Wolfcamp w/4'	including estimate proposed complete the com	ated date etion or n w/1 S
OTHER: 2. Describe proposed or completed starting any proposed work). SEI recompilation. 1/20/02 - MIRU. PU 4-3/4" bit, 5 ½ 1/21/02 - Ru Baker Atlas & ran CBL Perf 9104'-9110'. RIH w/ 1/23/02 - Swab. 1/27/02 - RU Baker Atlas. RIH w/C & pkr to 8942'. Swab. 2/02/02 - Acidize perfs from 9052'-92/04/02 - Swab. 2/10/02 - RU Hydro-Testers. TIH w/ 2/11/02 - Ran rods & pmp. LD & testers.	operations. (Clearly see RULE 1103. For Musical Section of the RULE 11	tate all pertialtiple Comp 'tbg. Tag F 83'-7700'. est csg. & test to 20	CASING TEST AI CEMENT JOB OTHER: nent details, and girpletions: Attach we PBTD @ 9184'. PUTOC @ 3470'. Pe	Completion ve pertinent dates, ellbore diagram of JH to 9125'. Pick rf Wolfcamp w/4'	including estimate proposed complete the com	ated date etion or n w/1 Sl
OTHER: 2. Describe proposed or completed starting any proposed work). SEI recompilation. 1/20/02 - MIRU. PU 4-3/4" bit, 5 ½ 1/21/02 - Ru Baker Atlas & ran CBL Perf 9104'-9110'. RIH w/1/23/02 - Swab. 1/27/02 - RU Baker Atlas. RIH w/C & pkr to 8942'. Swab. 2/02/02 - Acidize perfs from 9052'-92/04/02 - Swab. 2/10/02 - RU Hydro-Testers. TIH w/1/10/2 - Turn well over to production	operations. (Clearly see RULE 1103. For Mule" esg scraper on 2 7/8" L/GR/CCL log from 91 tbg & pkr to 9040". To EIBP set @ 9095". LD 9086" w/3400 gals 90/10 % tbg & set @ 9073". To st to 500 pis – Ok. on.	tate all perticultiple Comp 'tbg. Tag F 83'-7700'. est csg. & test to 20 10 15% HCI 'est, set TAG	CASING TEST AI CEMENT JOB OTHER: nent details, and girpletions: Attach we obtain the property of the property	Completion ve pertinent dates, ellbore diagram of JH to 9125'. Pick rf Wolfcamp w/4' hp w/2 JSPF (9052) H & pmpg tee.	including estimate proposed complete the com	ated date etion or n w/1 S
OTHER: 2. Describe proposed or completed starting any proposed work). SEI recompilation. 1/20/02 - MIRU. PU 4-3/4" bit, 5 ½ 1/21/02 - Ru Baker Atlas & ran CBL Perf 9104'-9110'. RIH w/1/23/02 - Swab. 1/27/02 - RU Baker Atlas. RIH w/C & pkr to 8942'. Swab. 2/02/02 - Acidize perfs from 9052'-92/04/02 - Swab. 2/10/02 - RU Hydro-Testers. TIH w/2/11/02 - Ran rods & pmp. LD & tested to the production of the	operations. (Clearly see RULE 1103. For Music Complete Indianation of the Rule 1103. For Music Complete Indianation of the Rule Indianation of the Rul	tate all perticultiple Comp 'tbg. Tag F 83'-7700'. est csg. & test to 20 10 15% HCI 'est, set TAG	CASING TEST AI CEMENT JOB OTHER: nent details, and girpletions: Attach we obtain the property of the property	Completion ve pertinent dates, ellbore diagram of JH to 9125'. Pick rf Wolfcamp w/4' hp w/2 JSPF (9052) H & pmpg tee.	including estimate proposed complete the com	ated date etion or n w/1 Sl
OTHER: 2. Describe proposed or completed starting any proposed work). SEI recompilation. 1/20/02 - MIRU. PU 4-3/4" bit, 5 ½ 1/21/02 - Ru Baker Atlas & ran CBL Perf 9104'-9110'. RIH w/1/23/02 - Swab. 1/27/02 - RU Baker Atlas. RIH w/C & pkr to 8942'. Swab. 2/02/02 - Acidize perfs from 9052'-92/04/02 - Swab. 2/10/02 - RU Hydro-Testers. TIH w/2/11/02 - Ran rods & pmp. LD & tested to the production of the	operations. (Clearly see RULE 1103. For Mule" esg scraper on 2 7/8" L/GR/CCL log from 91 tbg & pkr to 9040". To EIBP set @ 9095". LD 9086" w/3400 gals 90/10 % tbg & set @ 9073". To st to 500 pis – Ok. on.	tate all pertialtiple Comp ty the Tag F 83'-7700'. est csg. & test to 20 10 15% HCI est, set TAG	CASING TEST AI CEMENT JOB OTHER: nent details, and girpletions: Attach we obtain the property of the property	Completion ve pertinent dates, ellbore diagram of JH to 9125'. Pick rf Wolfcamp w/4' ap w/2 JSPF (9052) H & pmpg tee.	including estimate proposed complete the com	ated date etion or n w/1 SI
OTHER: 2. Describe proposed or completed starting any proposed work). SEI recompilation. 1/20/02 - MIRU. PU 4-3/4" bit, 5 ½ 1/21/02 - Ru Baker Atlas & ran CBL Perf 9104'-9110'. RIH w/1/23/02 - Swab. 1/27/02 - RU Baker Atlas. RIH w/C & pkr to 8942'. Swab. 2/02/02 - Acidize perfs from 9052'-92/04/02 - Swab. 2/10/02 - RU Hydro-Testers. TIH w/2/11/02 - Ru Hydro-Testers. TIH w/2/11/02 - Ru Hydro-Testers. TIH w/2/11/02 - Turn well over to production hereby certify that the information abuse of the property of the production of the property of the production of the	operations. (Clearly see RULE 1103. For Music Complete Indoor See RULE 1103. For Music Complete See Secretary of See Secretary of Secre	tate all perticultiple Comp 'tbg. Tag F 83'-7700'. est csg. & test to 20 10 15% HCI 'est, set TAG ete to the be	CASING TEST AI CEMENT JOB OTHER: nent details, and girpletions: Attach we pletions: At	Completion ve pertinent dates, ellbore diagram of JH to 9125'. Pick of Wolfcamp w/4' The pw/2 JSPF (9052) H & pmpg tee.	including estima proposed comple tbg. Predator csg gu	ated date etion or n w/1 SI
OTHER: 2. Describe proposed or completed starting any proposed work). SEI recompilation. 1/20/02 - MIRU. PU 4-3/4" bit, 5 ½ 1/21/02 - Ru Baker Atlas & ran CBL Perf 9104'-9110'. RIH w/1/23/02 - Swab. 1/27/02 - RU Baker Atlas. RIH w/C & pkr to 8942'. Swab. 2/02/02 - Acidize perfs from 9052'-92/04/02 - Swab. 2/10/02 - RU Hydro-Testers. TIH w/2/11/02 - Ru Hydro-Testers. TIH w/2/11/02 - Ru Hydro-Testers. TIH w/2/11/02 - Turn well over to production hereby certify that the information abuse IGNATURE	operations. (Clearly see RULE 1103. For Music Complete Indoor See RULE 1103. For Music Complete See Secretary of See Secretary of Secre	tate all perticultiple Comp 'tbg. Tag F 83'-7700'. est csg. & test to 20 10 15% HCI 'est, set TAG ete to the be	CASING TEST AI CEMENT JOB OTHER: nent details, and girpletions: Attach we obtain the production of th	Completion ve pertinent dates, ellbore diagram of JH to 9125'. Pick of Wolfcamp w/4' The pw/2 JSPF (9052) H & pmpg tee. e and belief. Est	ABANDONME including estima proposed compl le tbg. Predator csg gu 2'-9086'). RIH v	ated date etion or w/1 SI
OTHER: 2. Describe proposed or completed starting any proposed work). SEI recompilation. 1/20/02 - MIRU. PU 4-3/4" bit, 5 ½ 1/21/02 - Ru Baker Atlas & ran CBL Perf 9104'-9110'. RIH w/1/23/02 - Swab. 1/27/02 - RU Baker Atlas. RIH w/C & pkr to 8942'. Swab. 2/02/02 - Acidize perfs from 9052'-92/04/02 - Swab. 2/10/02 - RU Hydro-Testers. TIH w/2/11/02 - Ran rods & pmp. LD & tested to the production of the	operations. (Clearly see RULE 1103. For Music Complete Inc.) For Music Complete See Secretary of the Secreta	tate all perticultiple Comp ' tbg. Tag F 83'-7700'. est csg. & test to 20 10 15% HCI 'est, set TAC	CASING TEST AI CEMENT JOB OTHER: nent details, and girpletions: Attach we oblige a second of the control of the	Completion ve pertinent dates, ellbore diagram of JH to 9125'. Pick of Wolfcamp w/4' The pw/2 JSPF (9052) H & pmpg tee. e and belief. St	ABANDONME including estima proposed compl le tbg. Predator csg gu 2'-9086'). RIH v	ated date etion or w/1 SI
OTHER: 2. Describe proposed or completed starting any proposed work). SEI recompilation. 1/20/02 - MIRU. PU 4-3/4" bit, 5 ½ 1/21/02 - Ru Baker Atlas & ran CBL Perf 9104'-9110'. RIH w// 1/23/02 - Swab. 1/27/02 - RU Baker Atlas. RIH w/C & pkr to 8942'. Swab. 2/02/02 - Acidize perfs from 9052'-92/04/02 - Swab. 2/10/02 - RU Hydro-Testers. TIH w// 2/11/02 - Ran rods & pmp. LD & tested to the production of	operations. (Clearly see RULE 1103. For Music Complete Inc.) For Music Complete See Secretary of the Secreta	tate all perticultiple Comp 'tbg. Tag F 83'-7700'. est csg. & test to 20 10 15% HCI 'est, set TAG ete to the be	CASING TEST AI CEMENT JOB OTHER: nent details, and girpletions: Attach we obtain the production of th	Completion ve pertinent dates, ellbore diagram of JH to 9125'. Pick rf Wolfcamp w/4' ap w/2 JSPF (9052) H & pmpg tee. e and belief. st	including estima proposed comple tbg. Predator csg gu	nted date etion or n w/1 SF