

NO. OF COPIES RECEIVED		
DISTRIBUTION		
SANTA FE		
FILE		
U.S.G.S.		
LAND OFFICE		
OPERATOR		

NEW MEXICO OIL CONSERVATION COMMISSION

APR 17 3 01 PM '67

Form C-103
Supersedes Old
C-102 and C-103
Effective 1-1-65

5a. Indicate Type of Lease
State <input type="checkbox"/> Fee <input checked="" type="checkbox"/>

5. State Oil & Gas Lease No.

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR.
USE "APPLICATION FOR PERMIT - A" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER- <input type="checkbox"/>	7. Unit Agreement Name
2. Name of Operator	8. Farm or Lease Name
Morris R. Antweil	Floyd Vincent
3. Address of Operator	9. Well No.
Box 2010, Hobbs, New Mexico 88240	1
4. Location of Well	10. Field and Pool, or Wildcat
UNIT LETTER M , 660 FEET FROM THE South LINE AND 660 FEET FROM	Wildcat
West LINE, SECTION 11 , TOWNSHIP 7S , RANGE 32 E NMPM.	
15. Elevation (Show whether DF, RT, GR, etc.)	12. County
4474' DF	Roosevelt

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:	SUBSEQUENT REPORT OF:
-------------------------	-----------------------

PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input checked="" type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>	CASING TEST AND CEMENT JOBS <input type="checkbox"/>	

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

Propose to P & A as follows:

**Spot 25 sx. cement plug across perfs 4157' --4278'.
Cut and pull 4-1/2" casing from est. 4000'.
Spot 25 sx. cement plug across casing stub.
Spot 25 sx. cement plug across 8-5/8" casing shoe @ 3372'.
Spot 10 sx. cement plug at surface and erect marker.**

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED *R M Williams* TITLE **Agent** DATE **March 22, 1967**

APPROVED BY _____ TITLE _____ DATE _____

CONDITIONS OF APPROVAL IF ANY: